

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004


JUN 1 1 2003

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION	
busine DBS, MC4D	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO / 30-025-07609
DISTRICT II		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		STATE FEE X
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		Section 4
1. Type of Well:		8. Well No. 56
Oil Well Gas Well Other Injector		
2. Name of Operator		9. OGRID No. 157984
Occidental Permian Ltd.		
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	1	/
4 Well Location		
Unit Letter P : 660 Feet Fr	rom The South 660	Feet From The East Line
Section 4	Township 19-S Range 3. evation (Show whether DF, RKB, RT GR, etc.)	8-E NMPM Lea County
3611°		
Pit or Below-grade Tank Application on	r Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
	Grade Tank: Volume bbls; Construction	
Pit Liner Thickness mil Below-0	Grade Tank: Volume bols, Constitution	viateriai
12. Check Approp	riate Box to Indicate Nature of Notice, Report, o	or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
F		ALTERING CASING
TEN ON NEW ENGLAND		
TEMPORARILY ABANDON CHANG	GE PLANS COMMENCE DRILLING	OPNS PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple	Completion CASING TEST AND CEM	IENT JOB
OTHER.	OTHER. Clean or	ut/OAP/Acid Treat
13. Describe Proposed or Completed Operations (Complete Operations)	Clearly state all pertinent details, and give pertinent de	ites, including estimated date of starting any
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. NU BOP/ND wellhead.		
2. POOH w/tubing & injection equipment.		
3 RIH w/bit & drill collars. Tag fill @4180'.		
4 RU power swivel & stripper head. Drill out	@4180'. Clean out to 4191'. Tbg plugged. RD p	ower swivel & stripper head RU wireline and shoot
hole @3949'. RD wireline. NU power swivel	l & stripper head. Clean out iron sulfide from 4180	0-4200'. Drill out cement from 4200' to 4240',
Circulate clean. RD power swivel & stripper he		
5. RU pump truck & pump 5 bbl of acid from 4	1260-4202'. RD pump truck.	
6. POOH w/bit & drill collars.	Shoot morfo from 4202 002 4214 202 4222 262	no ISDE DD wirling
// KU wireline & log collars from 4230-3200'.	Shoot perfs from 4202-08', 4214-20', 4223-26' (acid treat well w/3000 gal of 15% NEFE acid and	500# rock salt RD HFS
8. KIH W/PYI packer set (#4086). KU HES &	acid fieat well w/2000 gal of 12/6 NETE acid alid.	ached sheet for additional data***
	See are	
I hereby certify that the information above is true and co	implete to the best of my knowledge and belief. I further cer	tify that any pit or below-grade tank has been/will be
constructed or	ampiece to the best of my knowledge and benefit. I future cer	
closed according to NMOCD guidelines	, a general permit or an (attached) alterna	tive OCD-approved
$\neg $	plan	
SIGNATURE NUMBER OF SIGNATURE Administrative Associate DATE 06/10/2008		
	/	,
TYPE OR PRINT NAME Mendy (A. Johnson	E-mail address: <u>mendy_johnson@oxy.c</u>	om TELEPHONE NO. 806-592-6280
For State Use Only	PE TROLEUM I	ENGINEER
APPROVED BY	TITLE	J WAN 1 8 2008
	<i>VII</i>	
CONDITIONS OF APPROVAL IF ANY:		

SHU 56

- 9. POOH w/PPI packer.
- 10. RIH w/5-1/2" Lokset packer on 123 jts of 2-3/8" IPC tubing.
- 11. ND BOP/NU wellhead & flowline.
- 12. Test casing to 600# and chart for the NMOCD.
- 13. RDPU & RU. Clean location.

RUPU 05/20/08 RDPU 05/27/08



and the second of the second o