State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION			
DISTRICT I 1625 N French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07609		
DISTRICT II	,		5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X	
DISTRICT III			6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410				Name of Name o	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			South Hobbs (G/SA) Unit Section 4		
1 Type of Well Oil Well Gas Well Other Injector			8. Well No. 56		
Name of Operator Occidental Permian Ltd.	· · · · · · · · · · · · · · · · · · ·			9. OGRID No. 157984	
3 Address of Operator HCR 1 Box 90 Denver City, TX 79323			10. Pool name or Wildcat	Hobbs (G/SA)	
4. Well Location					
Unit Letter P : 660 Feet From The South 660 Feet From The East Line					
Section 4	Township 19-S	Range 38-I	E NMPM	Lea County	
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3611' KB					
Pit or Below-grade Tank Application or Closure					
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS PLUG&	ABANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB					
OTHER: Clean out/OAP/Acid Trea		OTHER:			
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any					
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well.					
2. POOH w/injection equipment.					
Perforate well.					
 5. Acid treat well w/3000 gal of 15% NEFE HCI acid w/gelled rock salt block. 6. Run back in hole w/injection equipment. 					
7. Test casing and chart for the NMO			JUN 0 3 20	08	
		ı	HARRE	acn -	
Thomship court for that the information of	true and complete to the hart of week	ladge and ballof I forther and	that any not ar balance 1 - 1	has been/will be	
I hereby certify that the information above is true and complete to the best of my knowledge and belief I further certify that any pit or below-grade tank has been/will be constructed or					
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE Mundy	1 a Johnson	TITLE Administrative	Associate DA	TE <u>05/28/2008</u>	
	ollnson B-mail address:	mendy_johnson@oxy.com	TELEPHONE NO	0. 806-592-6280	
For State Use Only APPROVED BY	and	PETROLEUM E	NGINEER JU	N 1 8 2008	
CONDITIONS OF APPROVAL IF ANY:					
Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart.					