State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-26115	/
<u>DISTRICT II</u>	Small 4 Vy		5. Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreem	i
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			South Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 1. Type of Well:			Section 5 8. Well No 120	
Oil Well Gas Well Other Injector			0. 110 120	_
2 Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.			10. Pool name or Wildcat	H-11 (0/0A)
3 Address of Operator HCR 1 Box 90 Denver City, TX 793	23		10. Pool name or Wildcat	Hobbs (G/SA)
4. Well Location			<u> </u>	
Unit Letter C: 1272 F	Feet From The North	Line and 1420 Feet	From The West	Line
Section 5 Township 19-S Range 38-E NMPM Lea County				
Section 5 Township 19-S Range 38-E NIMPM Lea County 11. Elevation (Show whether DF, RKB, RT GR, etc.)				
3620' GL				
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
,				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PL	UG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT				
PULL OR ALTER CASING Mu	OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JO			
OTHER Clean out/OAP/Acid treat	X	OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
 Kill well. Drill and clean out to new PBTD @4265'. 				
3. Acid treat well.				
4. Perforate well.				
5. Acid treat new perfs. 6. Run back in hole w/injection equipment				
6. Run back in hole w/injection equipment. 7. Test casing and chart for the NMOCD. MAY 1 6 2004				
			VALUEDON TO THE PARTY TO THE PA	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or				
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	OCD-approved	
7	Y Oca L	plan		
SIGNATURE / MUNCLY	i allom	TITLE Administrative	Associate DATE	05/14/2008
TYPE OR PRINT NAME Mendy A. Johnson	<u> </u>			
	/ /	mendy_johnson@oxy.com	TELEPHONE NO.	806-592-6280
For State Use Only	/ /			01
	/ /	PETROLEUM EN		806-592-6280 N 1 8 2008
For State Use Only APPROVED BY CONDITIONS OF APPROVAL IF ANY:	/ /	PETROLEUM EN TITLE Notify OCD Hobbs	GINEER JUL	01