State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
<u>HOISTRICT I</u> 1625 N French Dr , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-28353	
DISTRICT II'			5. Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 88210			STATE X	FEE
<u>DISTRICT III</u>			6. State Oil & Gas Lease No	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			South Hobbs (G/SA) Unit	
1 Type of Well	APPLICATION FOR PERMIT (Form C-1	Section 10 8. Well No. 150		
Oil Well X	Gas Well Other		150	
2. Name of Operator	Gas Well Guide		9. OGRID No. 157984	
Occidental Permian Ltd.				
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, T	X 79323			
4. Well Location				
Unit Letter D . 330	Feet From The North	Fee	et From The West	Line
Section 10	Township 19-S	Range 38-I	E NMPM	Lea County
	11. Elevation (Show whether DF, RK	(B, RT GR, etc)		
	3621' KB			
Pit or Below-grade Tank Application	or Closure			
,	1 1		Distance from magnest	overfa a a vyatar
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	iterial	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF IN			SEQUENT REPORT (OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERIA	IG CASING
\equiv				ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP		ABANDONWENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	IT JOB	
OTHER: Convert to ESP from Be	eam X	OTHER		
13. Describe Proposed or Completed C	Operations (Clearly state all pertinent de	tails, and give pertinent dates	including estimated date of	starting any
proposed work) SEE RULE 110	3. For Multiple Completions: Attach w	vellbore diagram of proposed	completion or recompletion.	
1. Kill well. POOH w/tubing and b	eam production equipment. I out CIBP & clean out to TD @4349	O' Cura alaam	OCCE	INDEED TO
3. Perforate well.	Tout CIBF & clean out to 1D @4545	9. Circ cicaii.	RECE	INED
4. Acid treat.				
Perform scale squeeze.			APR 2.8	9 ľ \ 6 Ø
6. Run in hole w/ESP equipment.			MIN Z. ()	(LUC)
7. Return well to production.			LIADDO	: Mor
			MUDDE	
I hereby certify that the information above constructed or	is true and complete to the best of my know	ledge and belief I further certify	that any pit or below-grade tank	has been/will be
closed according to NMOCD guideline	, a general permit	or an (attached) alternative	e OCD-approved]
SIGNATURE Munch	of a Johnson	TITLE Administrative	Associate DA7	ΓΕ <u>04/23/2008</u>
TYPE OR PRINT NAME Mendy A	Johnson E-mail address:	mendy_johnson@oxy.com	TELEPHONE NO	0. 806-592-6280
For State Use Only	7. /			
APPROVED BY	and	TITLE PETROLEUM	ENGINEER J	UN 18 2008
				

CONDITIONS OF APPROVAL IF ANY: