

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No 1004-0135  
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

LANEXCO, INC.

3. Address and Telephone No.

1105 WEST KANSAS, JAL, NM 88252 505-395-3056

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL: I, 660', FEL, 1980' FSL

Sec. 11, T25S, R37E

5. Lease Designation and Serial No.

NM-0140977

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

JUSTIS A FED. #1

9. API Well No.

30-025-26484

10. Field and Pool, or Exploratory Area

Langlie Mattix; 7 Wells -

11. County or Parish, State

LEA, NM

Grayburg

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

05-13-08: MIRU. ND well haed. NU BOP. Run in hole with MMCPI workstring. Tag @ 3082'. Circulate plugging mud. Spot 25 sxs with CAGE2 @ 3081'. PULL OUT HOLE. WOC. SDFD.

05-14-08: Run in hole and tag @ 2725'. Pull up hole to 2303'. Spot 25 sxs. Pull out of hole. WOC. Run in hole and tag @ 2051'. Pull up hole to 486'. Spot 40 sxs. Pull out of hole to 97'. Circulate 15 sxs to surface. SDFD.

05-15-08: Rig down. Cut well head off. Cut off anchors. Install dryhole marker. Level ~~production~~ location. SDFD.

RECEIVED

JUN 10 2008

HOBBS OCD

ACCEPTED FOR RECORD

JUN 7 2008

J. Amos

14. I hereby certify that the foregoing is true and correct

Signed

*Chris L. Munn*

Title PRODUCTION SUPT.

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD

Date 05-22-08

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

*KZ*

Title

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

\*See instruction on Reverse Side