



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

19-Jun-08

KEVIN O BUTLER & ASSOC INC

500 W. TEXAS STE 955

MIDLAND TX 79701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

| STATE R No.001 | | | | K-27-14S-33E | 30-025-01155-00-00 | |
|--|------------------|-------------|------------|------------------------------|---------------------------|----------------|
| Inspection Date | Type Inspection | Inspector | Violation? | *Significant Non-Compliance? | Corrective Action Due By: | Inspection No. |
| 06/19/2008 | Routine/Periodic | Maxey Brown | Yes | No | 9/22/2008 | iMGB0817158261 |
| Violations | | | | | | |
| Absent Well Identification Signs (Rule 103) | | | | | | |
| Surface Leaks/Spills | | | | | | |
| General Housekeeping (Rule 114) | | | | | | |
| Comments on Inspection: Location needs attention. Equipment OK. RULE 114. NEED TO REMOVE SURPLUS RODS AND THREAD PROTECTORS FROM SOUTHSIDE OF LOCATION. ALSO NEED TO CORRECT SIGN AT TANK BATTERY TO REFLECT CURRENT OPERATOR. RULE 103. NEED TO REPAIR WATER TANK SEEPS AROUND BOTTOM CHIME. RULE 116. (TRUCK TRACKS AROUND TANK). THIS IS 1ST LETTER OF NON-COMPLIANCE. | | | | | | |

STATE R No.003

B-27-14S-33E


30-025-01157-00-00

| Inspection Date | Type Inspection | Inspector | Violation? | *Significant Non-Compliance? | Corrective Action Due By: | Inspection No. |
|---------------------------------|------------------|-------------|------------|---------------------------------|------------------------------|----------------|
| 06/19/2008 | Routine/Periodic | Maxey Brown | Yes | No | 9/22/2008 | iMGB0817160114 |
| Violations | | | | | | |
| General Housekeeping (Rule 114) | | | | | | |

Comments on Inspection: Location needs attention. Equipment OK. RULE 114. NEED TO REMOVE SURPLUS TUBING AND LOOSE THREAD PROTECTORS FROM NORTHSIDE OF WELL. THIS IS 1ST LETTER OF NON-COMPLIANCE.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



| | | |
|--------|-------------------|------------|
| HASLER | 014415215335 | US POSTAGE |
| | \$0.420 | |
| | 06/19/2008 | |
| | Mailed From 88240 | |

KEVIN O BUTLER & ASSOC INC
500 W. TEXAS STE 955
MIDLAND TX 79701