



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

26-Jun-08

ASHER ENTERPRISES LTD. CO.

12808 LORIEN WAY

OKLAHOMA CITY OK 73170

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

STATE 1 No.001				E-2-24S-34E	30-025-24319-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/24/2008	Compliance Verification	Buddy Hill	Yes	No	7/22/2008	iLWH0817658436
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		NEW WELL SIGN @ WELL SAYS FOR "STATE 35 #001, NO SIGN AT BATTERY..PER LETTER DATED 6-9-08 BY KELLYE JONES..MEET ON LOCATION FOR RE-INSPECTION.,SECOND NOTICE				

STATE 2 No.002				K-2-24S-34E	30-025-24414-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/24/2008	Compliance Verification	Buddy Hill	Yes	No	7/22/2008	iLWH0817658797
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		No Well Sign (Rule 103). PER LETTER DATED 6-9-08 BY KELLYE JONES, WELL SIGN IS GONE, NO SIGN AT BATTERY..MEET ON LOCATION FOR RE-INSPECTION..SECOND NOTICE				

STATE 35 No.001

K-35-23S-34E

30-025-24517-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/24/2008	Compliance Verification	Buddy Hill	Yes	No	7/22/2008	iLWH0817657842
Violations Absent Well Identification Signs (Rule 103)						

Comments on Inspection: PER LETTER DATED 6-9-08, SIGNED KELLYE JONES..WELL SIGN HAS NOT BEEN CORRECTED..KELLYE JONES IS REQUIRED TO BE ON LOCATION FOR RE-INSPECTION..SECOND NOTICE

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER
014115215335
\$0.420
06/26/2008
Mailed From 88240
US POSTAGE

ASHER ENTERPRISES LTD. CO.
12808 LORIEN WAY
OKLAHOMA CITY OK 73170