

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36909
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VO-6919-0000
7. Lease Name or Unit Agreement Name <i>New Mexico "36" State</i> State of New Mexico 36
8. Well Number 2
9. OGRID Number 151323
10. Pool name or Wildcat Skaggs: Drinkard <i>57000</i>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,600' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Pride Energy Company	
3. Address of Operator P.O. Box 701950, Tulsa, OK 74170	
4. Well Location Unit Letter <u>O</u> : 990 feet from the <u>South</u> line and <u>2,310</u> feet from the <u>East</u> line Section <u>36</u> Township <u>19 South</u> Range <u>37 East</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,600' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Temporarily Abandon ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Called OCD Hobbs District Office 24 hrs. prior to beginning work in order to give notice.
2. RUPU, bled off pressure, ND wellhead, NU BOP, RU wireline, TIH W/ gauge ring, TOH & P/U 5 1/2" CIBP, TIH & set CIBP @ 4,230', RD wireline.
3. ND BOP, NU wellhead, RDPU, RU pump truck, displaced 5 1/2" casing w/ packer fluid, pressure tested casing to 520# psi for 30 mins. W/ chart recorder, tested good, shut down (chart is attached to this report) 6/18/08-6/19/08 work performed.

RECEIVED

JUN 27 2008

HOBBS OCD

TA expires
6/27/2013
del

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

John W. Pride

SIGNATURE John W. Pride TITLE Pres. Of Pride Oil & Gas Co., Inc., as Gen. Partner of Pride Energy Company DATE June 26, 2008

Type or print name John W. Pride E-mail address: johnp@pride-energy.com PHONE: 918-524-9200

For State Use Only

APPROVED BY: *Chris Williams*
Conditions of Approval (if any):

OCD DISTRICT SUPERVISOR/GENERAL MANAGER

JUN 27 2008

