Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

JUN 0 5 2008 OCD-ARTES

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side					
				7. If Unit or CA/Agreement, Name and/or No	
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator OXY USA Inc. 3a. Address P.O. Box 50250 Midland, TX 7971	16696 3b. Phone No. (include area code) 432-685-5717		8. Well Name and No. Covington A 10 Federal 9. API Well No. 30-025-32581 10. Field and Pool, or Exploratory Area Red Tank Delaware, West 11. County or Parish, State Lea NM		
4. Location of Well (Footage, Sec., T., R., M., or Survey 1 660 FSL 1980 FEL SWSE(0) Sec 25 T					
12. CHECK APPROPRIATE	BOX(ES) TO IND	DICATE NATURE OF	NOTICE, REF	PORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injectic	Deepen X Fracture Treat New Construction Plug and Abandon Plug Back	Reclamati	ete	Water Shut-Off Well Integrity Other
If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment Metermined that the final site is ready for final inspection of the involved operations. I testing has been completed. Final Abandonment Metermined that the final site is ready for final inspection. 1. Check for overhead power lines. 2. POOH w/ lift equipment. 3. RIH w/ PKR & RBP to straddle pe 4. FRAC Ramsey as follows, Air 15-a.1500 Gals Linear Prepad b.4000 Gals X-Link Pad c.5000 Gals X-Link Pad c.5000 Gals X-Link W/ 20-25M# 1 d.Flush w/ Linear Gel to Packer e.Force Close 5. POOH w/ pkr 6. Clean out sand to top of RBP. 7. Swab Ramsey formation to check 8. Clean well out to CIBP set at 8. 9. RIH w/ new lift design and place 10. RDPU. 14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart THIS	formed or provide the If the operation results in Notices shall be filed on ection.) Check wellhead rfs at 5018-28' 20 BPM. 6/30 SLC Ramped for sand. POOH 800'. e well on product	and No. on file with BLM. In a multiple completion or r ly after all requirements, in d pressure. RUPU. I test tbg and RBP 1-10 PPG W/RBP. Ction. Title Sr. Re	egulatory An	subsequent reports shew interval, a Formion, have been comp	nall be filed within 30 days 13160-4 shall be filed once eleted, and the operator has
Approved by		Title		Date	
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the	those rights in the subje	CT SUPERVISOR/GE arrant or Office ect lease	PHERAL MAN	IACED	