Submit 3 Copies To Appropriate I Office	State of New		Form C-103
District I Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION		TON DIVISION	30-025-32922
1301 W Grand Ave., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE   6. State Oil & Gas Lease No.	
District IV 1220 S. St Francis Dr., Santa Fe, NM 87505			B-2148
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Group Concerns (Concerns)			8. Well Number 139
2. Name of Operator Forest Oil Corporation			9. OGRID Number 8041
3. Address of Operator			10. Pool name or Wildcat
707 17 <sup>th</sup> Street, Suite 3600, Denver, Colorado			Maljamar Grayburg San Andres
4. Well Location			
Unit Letter: <u>G</u> feet from <u>2603</u> line and <u>North</u> feet and <u>1358</u> from the <u>East</u> line			
Section 18 Township 17S Range 33E NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4194 GR			
Pit or Below-grade Tank Application or Closure			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness:     mil     Below-Grade Tank: Volume     bbls;     Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			SEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING		CASING/CEMEN	Т ЈОВ 🗌 —
		OTHER: 🛛 Ad	dded Perfs, Acdz and Return to Produciton
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
6-9-08 – Move rig to location. 6-10-08 – LD PR work w/ pmp it was stuck, broke loose, POH rods & pmp 1 1/4 PR, w/ 1 1/2 x 16' PRL, 2' x 1" sub, 79 - 1" rods, 95 - 7/8			
rods, 2 1/2 x 1 1/2 x 20 pmp, GA 12' x 1 1/4 .ND WH NU BOP unset TAC POH tbg & tally 124 jts 2 7/8 to TAC, 126 jts to S.N. 4'x 2 7/8 perf			
sub, 1 - mud jt B.P. 6-11-08- RU reverse unit , fill pit w/ 1oo bbls_wtr, pick up 4 - DC w/ 4 3/4 bit RIH w/ 132 jts , drill hard scale, bridges , @ 4570' fail through ,			
drill to 4607' circulate hole clean, POH 8 stands, S.I.			
6-12-08 - Pull out 30 bbls from work pit bleed pres, RIH w/ 8 stands RU swivel start cir. & drilling tag @ 4580', fail through drill hard scale,			
to 4880' pick up swivel 2' from bottom , cir. clean POH w/ 151 jts 2 7/8 LD 4 DC S.I. 6-13-08 - acdz perf 4531'- 4781' w/ 5250 15 % gals nefe & 2000 # rock salt, RIH 5 1/2 lok set RBP arrow set pkr 143 jts 2 7/8 tbg set			
4520' POH set pkr @ 3989', second stage acidize 4105' - 4505' w/8500 gals 15 % nefe acid w/ rock salt, total bbls to recover 567 bbls.			
6-14-08 -  Check tbg pres, 1500 # bleed tbg to frac tk flow back, 152 bbls log gas, 2 % oil cut, 6-18-08 -  RU swab tool & started swabing , total swab 105 bbls 2 % oil cut low gas, total to recover 108 bbls.			
6-19-08 - Open well flow 5 bbls , swabing , swab 95 bbls , 2 % oil cut low gas , POH tbg LD pkr , put retrivel head RBIH w/ 44 stands			
6-20-08 - open well tbg had 250 #, pmp 10 bbls 2 % kcl wtr, tbg flowing pmp 28 bbls brine wtr, tbg went on vacuum, RIH 2 7/8 tbg tag up @ 4480', RU Key pmp trk cir, salt out to 4520', cir, well clean unset RBP POH LD 2 7/8 tbg out of hole w/ tbg & RBP			
6-23-08 RU tbg tester, RU vacuum trk, test tbg BIH, 124 jts, 2 7/8 tbg , tbg test good , ND BOP set TAC, NU WH , pick up pmp & rods			
RBIH , hang well, RD PU clean loc. left unit running. Put back on Production.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines 🖾, a general permit 🗌 or an (attached)alternative OCD-approved plan 🗌.			
SIGNATURE			
Type or print name Cindy Bush E-mail address: cabush@forestoil.com Telephone No. 303-812-1554 L 7 5 2008			
For State Use Only APPROVED BY: Chus Clelliems TITLE DATE			

Conditions of Approval (if any):