	Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103	
-	District I	Energy, Minerals and Natural Resources		May 27, 2004	
+	1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION		30-025-31981	
	1301 W Grand Ave., Artesia, NM 88210 District III	1220 South St. Fran		5. Indicate Type of Lease STATE STATE	
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM 87505	ير	- STU	B-2148	
ſ	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEREN OR PLUE BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORMIC ON) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Confer			7. Lease Name or Unit Agreement Name	
			R SUCH	Caprock Maljamar Unit 8. Well Number	
			19 - 20	128	
ŀ	2. Name of Operator	147	A A	9. OGRID Number	
ļ	Forest Oil Corporation			10. Pool name or Wildcat	
	3. Address of Operator 707 17 th Street, Suite 3600, Denv	er, Colorado		Maljamar GBR-SA	
-	4. Well Location				
	Unit Letter: <u>H</u> feet from the <u>1365</u> line and <u>North</u> feet and <u>1260</u> from the <u>East</u> line				
Section 18 Township 17S Range 33E NMPM					
	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4189 GR				
Pit or Below-grade Tank Application or Closure				Projekt Print Stateman Strategy 7 V. A stateman Strategy	
	Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
			COMMENCE DRI		
	OTHER:			Turn back to Production	
	 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dates of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion. 5-23-08 - RU PU, POH rods, pmp, ND WH unset TAC, POH tbg, pick up scrapper w/ 4 3/4 bit & pick work string RBIH,110 jts 2 7/8 tbg. 5-27-08 - PU 23 jts & tag @ 4171' w/ 132 jts, stop & POH tbg & drill bit , PU 4 drill collars & drill bit 4 3/4 , RBIH w/ 126 jts 2 7/8 tbg. 5-29-08 - RBIH 5 stands RU swivel drill & tag @ 4422', drill to 4433' fail through gas pocket , 800 PSI , bleed down, drill to 4474' circ. was big pieces of hard medal, & white little rock, circ.hole clean, POH tbg. 5-30-08 - Bleed well down , RIH w/ 4 1/2 "rock bit , 4 - 3 1/2 drill collars on 2 7/8 tbg RU swivel , catch circ., clean out @ 4474' , fell through @ 4478', RIH & tag sand & fill @ 4815' , clean out to 4870' , circulated clean, RD swivel . 6-2-08 - RU WL, perf, shot 60 holes, POH guns, RBIH gauge ring to 4474', POH, RD WL pick up AD-1 pkr - 5 1/2 RBIH & test tbg , set @ 3990', RD tbg tester 6-3-08 - MIRU Raising Star, started acdz from 4789' to 4114' made 8 stages of acid & 7 blocks stages of rock salt, 7500 # & 16500 gals 0f 15 % HCL acid, ISIP 2360 psi, avg rate 4.7 bpm, max rate 5.0 bpm, avg pres 2550psi, max pres 2810 psi, flow well back in frac tk 445 bbl: tbg pres @ 80 psi, total bbls to recover 538 bbls. 6-4-08 - bleed well to frac tk flow 177 bbls, total back flow, 613 bbls, total to recover 538 bbls, over load 75 bbls 6-5-08 - RU pup trk, pupp 30 bbls back side & 20 bbls brine wtr on tbg, went on vacuum , release pmp trk POH 30 jts , well started flowing flowing and pupp trk. 				
 call pmp trk back, pump 40 bbls brine wtr, went on vacuum, POH rest of work string, 2 7/8 LD w/ pkr. RU tbg tester, RD tbg tester, N BOP set TAC NU WH, tie tbg to flow line. 6-9-08 - RU pmp trk, pump 20 bbls brine wtr kill well, pick up pmp, RBIH w/ rods, hang well RD vacuum trk, RD PU assemble well h clean location M.O. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or 				_D w/ pkr. RU tbg tester, RD tbg tester, ND	
				RD vacuum trk, RD PU_assemble well head ,	
				e and helief. I further certify that any nit or helow-	
grade tank has been/will be constructed or closed according to NMOCD guidelines 🖾, a general permit 🗌 or an (attached) alternative OCD-approved p					
	SIGNATURE mode	- Dushelle S	r. Regulatory Tech	DATE 78-08	
	Type or print name Cindy Bus	sh E-mail address: cabush	(a) forestail com	Telephone No. 303-812-1554	
	Type or print name Cindy Bus For State Use Only I	11.	0	111 170000	
	APPROVED BY: Mus	Williams OC PHERCI	SUPERVISOR/GE	VERAL MANAGE DATE DATE	