UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HOEBS

FORMAPPROVED OM B No 1004-0137 Expires: March 31, 2007

5. Lease Senal No.

NMLC-032096-B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

6 If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s	uch proposals.	
SUBMIT IN TRIPLICATE - Other instructions of	DOWN WILLIAM	7 If Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other JUL	2 1 2008	8 Well Name and No.
2. Name of Operator Apache Corporation	PSOCE	East Blinebry Drinkard Unit #66 9. API Well No 30-025-38761
3a. Address 3b. Phóite No. Yinclitale area code) 6120 S Yale Ave, Suite 1500 Tulsa OK 74136-4224 (918)491-4864		10 Field and Pool, or Exploratory Area Eunice; Blinebry-Tubb-Drinkard, N
4 Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit A, 1060' FNL and 1005' FEL, S 11, T 21S, R 37E		11. County or Parish, State Lea, NM
12. CHECK APPROPRIATE BOX(ES)TO INDICATE	NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Acidize Deepen Notice of Intent Alter Casing Fracture T Subsequent Report Casing Repair New Cons Change Plans Plug and A Final Abandonment Notice Convert to Injection Plug Back	struction Recomplete Abandon Temporarily Ab	Well Integrity X OtherCompletion pandon Procedure
If the proposal is to deepen directionally or recomplete horizontally, give subsurfaction that the Bond under which the work will be performed or provide the Bond Norlowing completion of the involved operations. If the operation results in a mutesting has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.) 05/20/08 Perf Drinkard @ 6648-52, 74-80, 6718-24, 56-605/21/08 Acidize Drinkard w/ 3000 gals 15% HCl. 05/22/08 Frac Drinkard w/ 43K gals gel and 62K # 20/40 05/27/08 Perf Tubb @ 6152-56, 6211-17, 6292-96, 6342 05/27/08 Set RBP @ 6380'. 05/28/08 Acidize Tubb w/ 3000 gals 15% HCl. 05/29/08 Frac Tubb w/ 36K gals gel and 62K # 20/40 sar 05/30/08 POH RBP @ 6380'. 05/30/08 Perf Blinebry @ 5690-94, 5746-52, 5806-12, 59 05/30/08 Set RBP @ 5975'. 06/02/08 Acidize Blinebry w/ 3000 gals 15% HCl. 06/03/08 Frac Blinebry w/ 37K gals gel and 66K # 20/40 s 06/04/08 POH RBP @ 5975'. RIH w/ production tubing, p 06/05/08 Set 640 pumping unit. Shut well in due to gas p 06/09/08 Place well on production from the Blinebry/Tubb	No. on file with BLM/BIA. Requitiple completion or recompletion all requirements, including reclar (32' w/ 2 JSPF.) sand. -46' w/ 2 JSPF. and. 906-12' w/ 2 JSPF.	nired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once
Name (Printed/Typed) Sophie Mackay	Title Engineering Te	ch
Signature Sonhie Mackay	Date 06/10/2008	100EDTED
THIS SPACE FOR FEDERAL	OR STATE OFFICE	VSECEPTED FOR RECORD
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for at States any false, fictitious or fraudulent statements or representations as to any	lease Office ny person knowingly and willfully	BUREAU OF LAND MANAGEMENT
(Instructions on page 2)		CARLSBAD FIELD OFFICE