

NEW MEXICO, ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop Cabinet Secretary HEALTO BEHALFORD

Mark E. Fesmire, P.E. Director

Oil Conservation Division

Response Required - Deadline Enclosed

16-Jul-08

PLATINUM EXPLORATION INC 550 WEST TEXAS AVENUE SUITE 500 MIDLAND TX 79701

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fc to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

KINSOLVING 6 001

C-6-12S-38E

30-025-32644-00-00

Inspection No. iMGB0819841939

Inspection Date:

7/16/2008 11:38:53 AM

Corrective Action Due by: 10/19/2008

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Routine/Periodic

Yes

No

Comments on Inspection:

Maxey Brown

Idle Well (Rule 201) NEED TO PUT WELL ON PROD., T/A OR P/A WELL. ALSO OPEN

DRILLING PIT NEEDS TO BE CLOSED. RULE 17. NEED TO INSTALL WELL SIGN. RULE

103.THIS IS 1ST LETTER OF NON-COMPLIANCE.

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Hobbs OCD District Office

Majey Brown
COMPLIANCE OFFICER

^{*} Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



017H15554612 \$0.420 07/17/2008 Mailed From 88240

PLATINUM EXPLORATION INC 550 WEST TEXAS AVENUE SUITE 500 MIDLAND TX 79701