Form 2160 5					OCD	1406 bs	
Form 3160-5 (August 2007)		UNITED STATES EPARTMENT OF THE INTERIOR FUREAU OF LAND MANAGEMENT			FORM APPROVED OMB NO 1004-0135 Expires: July 31, 2010		
		NOTICES AND REPORTS ON WELLS			5 Lease Serial No. NMLC064150		
	Do not use thi abandoned wel	s form for proposals to dr I. Use form 3160-3 (APD)	ill or to re-enter an for such proposals.	6. If Indian, Allottee or Tribe Name			
	SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. NMNM70988X					
	☐ Gas Well ☑ Oth		8. Well Name and No. MALJAMAR GB UN 59				
2. Name of Opera FOREST OI	ntor L CORPORATION	9. API Well No. 30-025-20760-00-S1					
DENVER, C		10. Field and Pool, or Exploratory MALJAMAR					
	ell (Footage, Sec., T		11 County or Parish, and State				
Sec 10 T179	S R32E NESW 19	LEA COUNTY, NM					
Uni $+$ K 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF S	UBMISSION		TYPE O	F ACTION			
Notice of I	l	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	Reclam Recomp			
Attach the Bon following comp testing has bee	is to deepen directions id under which the wor pletion of the involved	ration (clearly state all pertinent d. Illy or recomplete horizontally, giv k will be performed or provide the operations. If the operation result andonment Notices shall be filed onal inspection)	e subsurface locations and measi Bond No. on file with BLM/BL s in a multiple completion or rec	ured and true vo A. Required su completion in a	ertical depths of all perting bsequent reports shall be new interval a Form 316	nent markers and zones of filed within 30 days of 60-4 shall be filed once	
		* SEE ATT	ACHED FOR	r			
Plugging pro	ocedure:	CONDITI	ONS OF APPROV	AL	APPRO)VED	
★ 2 RIH w/tul★ 3. Displace★ 4. Displace★ 5. Displace	bing, set cement p wellbore w/heavy wellbore w/heavy	le equipment as required. lug from PBTD to 3,600' mud. Set cement plug botto mud. Set cement plug botto mud. Set cement plug botto	om @800', top @ 545'		JUL 1 (JAMES A. SUPERVIS	AMOS OR-EPS	

14 Thereby certify	that the foregoing is true and correct Electronic Submission #61271 veri For FOREST OIL CORP Committed to AFMSS for processing by I	ORATION.	. sent to the Hobbs	SE)			
Name (Printed/Typed) CINDY A BUSH			Title SR. REGULATORY TECH				
Signature	(Electronic Submission)	07/08/2008					
	THIS SPACE FOR FEDE	RAL OR	STATE OFFICE USE				
Approved By (BLM Approver Not Specified)		Tıtle		Date 07/19/2(
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			e Hobbs				

Additional data for EC transaction #61271 that would not fit on the form

32. Additional remarks, continued

7. Remediate surface location as necessary.

Wellbore Diagrams attached.



Forest Oil Corporation NMLC064150; Maljamar Greyburg Unit 59 1980' FSL & 1980' FWL Section 10, T.17 S., R.32 E. Lea County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

- 1. OK as is.
- 2. Records indicate a CIBP @ 3800' with 10 sxs cement on top (TOC est. 3704'). RIH and tag TOC. If something different contact Jim Amos at 505-234-5909.
- 3. Spot a balanced plug (minimum of 25 sxs) from 2280'- 2160' (Base of Salt). WOC and tag no lower than 2160'.
- 4. Perforate the 5-1/2" casing @ 1160', squeeze adequate cement to fill 100' in/out of the 5-1/2" casing (Top of Salt). WOC and tag no lower than 1060'.
- 5. Perforate the 5-1/2" casing @ 347, circulate cement to surface in/out of the 5-1/2" casing.

See attached standard COA's.

James A. Amos 505-234-5909

7/16/08



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972



Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

