State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE OIL CONSERVATION DIVISION					
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505		WELL API NO.	WELL API NO. 30-025-05486	
DISTRICT II	, , , , , , , , , , , , , , , , , , ,		5. Indicate Type of Lease	5. Indicate Type of Lease	
811 S. 1st Street, Artesia, NM 88210	*		FED STATE	X FEE	
DISTRICT III			6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410					
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreeme	7. Lease Name or Unit Agreement Name	
(FORM C-101 FOR SUCH PROPOSALS.)			NODTH HODDS (G/SA)	NORTH HOBBS (G/SA) UNIT	
1. Type of Well:	(LOIDE OF TON SCOTT ROLOSSES)			JINII	
Oil Well X Ga	s Well Other				
2. Name of Operator			8. Well No. 441		
OCCIDENTAL PERMIAN LTD. 3. Address of Operator			O Deal name of Wildow	TYODDO (O/O.)	
1017 W. Stanolind Rd., HOBBS, NM 882	10 505/30	7-8200	9. Pool name or Wildcat	HOBBS (G/SA)	
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location					
Unit Letter P : 330 Feet	From The SOUTH	Line and 330	Feet From The EAST	Line	
Section 24	Township 18S	Range	37E NMPM	LEA County	
10. E 3662	levation (Show whether DF, RK	B, RT GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON CHANG	SE PLANS	COMMENCE DRILLING	OPNS DILIGRAL	BANDONMENT	
PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB					
	· [MEN I JOB		
OTHER: Deepen and run Liner	X	OTHER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
Pull production equipment.					
 Deepen from 4214 to 4300 (still within unitized San Andres formation). 					
1. Pull production equipment. 2. Deepen from 4214 to 4300 (still within unitized San Andres formation). 3. Run 5-1/2" liner. 4. Perforate and acid stimulate. 5. Run production equipment and return well to production.					
4. Perforate and acid stimulate.					
5. Run production equipment and return well to production.					
	•		88 Mil 201	<u>0</u>	
			Secretary OCD Propose	المعم	
			4 Hopps	100 100 100 100 100 100 100 100 100 100	
			/55' 000	~~/ ~~/	
			\c 2 \		
			11819505	100	
^					
Thombsondiff that the Asia Asia Asia	1				
I hereby certify that the information above is true and cor	plete to the best of my knowled	ge and belief.			
SIGNATURE SIGNATURE		TITLE PROD ENG	R DATE	9-24-03	
TYPE OR PRINT NAME D. NELSON			TELEPHONE NO.	505/397-8200	
(This space for State Use)	110				
APPROVED BY LOUIS DATE NOV 0 3 2003					
CONDITIONS OF APPROVAL IF AND:					