

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
RECEIVED
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBS OCD

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-27992
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E3145
7. Lease Name or Unit Agreement Name: Coquina State
8. Well No. 1
9. Pool name or Wildcat San Simon; Yates North (Assoc)

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Marks and Garner Production Ltd. Co.

3. Address of Operator
P.O. Box 1089, Hobbs, NM 88241

4. Well Location

Unit Letter H, 1980 feet from the North line and 660 feet from the East line

Section 19 Township 21S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

REVISED PLUGGING PROCEDURE:

Set CIBP @ 3600' ± and cap with 35' cement.

Tag cement on CIBP.

Circulate hole with mud gel.

Spot 25 sx plug at base of salt approximately 1600'.

Fill casing from 400' to surface with cement.

Cut off wellhead; weld on dry hole marker 3' below surface.

Clean location and remediate.

RECEIVED

AUG 14 2009

HOBBS OCD

The Oil Conservation Division **Must** be notified 24 hours prior to the beginning of plugging operations

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra McKelvey TITLE AGENT DATE 8/12/08

Type or print name Quinton Welborn

Telephone No. 575-393-9358

(This space for State use)

APPROVED BY Chris Williams

OC DISTRICT SUPERVISOR/GENERAL MANAGER

Conditions of approval, if any:

AUG 18 2008

Coquina State I
Proposed PTA

