

RECEIVED

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
APR 22 2003
OIL CONSERVATION DIVISION
2201 South St. Francis Dr.
HOBBS 000
Santa Fe, NM 87505

Form C-103
March 4, 2004

WELL API NO. 30-025-28608
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name New Mexico St. D.L.
8. Well Number 3
9. OGRID Number 122811
10. Pool name or Wildcat Cruz Delaware

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Pronghorn Management Corporation	
3. Address of Operator P. O. Box 1772 Hobbs, NM 88241	
4. Well Location Unit Letter H : 1980 feet from the North line and 330' feet from the EAST line Section 18 Township 23 S Range 33 E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Return well to production ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Move in and rig up. POOH with rods and pump. (Rods parted).
Install B.O.P. POOH with tubing. Make bit & scraper run. TIH with tubing and packer. Pressure test casing above and below perms.--OKAY. POOH.
TIH with tubing. Take off B.O.P. TIH with rods and pump. Nipple up well head.
Return well to production. Rig down. Move out. Clean Location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE G. A. Baber TITLE PARTNER DATE 04/12/08
Type or print name G. A. Baber E-mail address: Telephone No. 575-392-2495

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

DENIED