

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-06024
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Bertha J. Barber
8. Well Number 10
9. OGRID Number 147179
10. Pool name or Wildcat Monument; Paddock & Blinbry

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Bertha J. Barber
2. Name of Operator Chesapeake	8. Well Number 10
3. Address of Operator	9. OGRID Number 147179
4. Well Location Unit Letter E : 330 feet from the West line and 1650 feet from the North line Section 8 Township 20S Range 37E NMPM Lea County	10. Pool name or Wildcat Monument; Paddock & Blinbry
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL: 3551'	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Notice of T.A. ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/02/03 Basic Well Service #1253

Load hole w/60 bbls pkr fluid, test plug to 500PSI, OK, pull out of hole w/tbg, rig up rotary wire line, run in hole w/bailor w/cement, dump 30' cmt on top of plug at 5045', rig down, trip in hole w/tbg to 5015' displace hole w/90 bbls pkr fluid, come out of hole laying down tbg, take BOP off, flange well up, 2 Load w/24 bbls pkr fluid, test to 500 PSI, OK, RDMO Leave well T.A.

This Approval of Temporary
Abandonment Expires 11/7/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Barbara J. Bale TITLE Regulatory Analyst DATE 10/08/03

Type or print name Barbara J. Bale E-mail address: _____ Telephone No. (405) 848-8000

(This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE NOV 10 2003

Conditions of approval, if any:

