J OCT-31-2003 11:	54 (	OCA-H	lobbs				P.02	
Form 3160-5 UNITED STATES (August 1999) DEPARTMENT OF THE INTERIOR						FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS						5. Lease Serial No. LC 031695B		
Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name			
abandoned w	rell. Use Form 3160-3 (A	PD) for such p	proposals.					
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No. Warren Unit Blinebry-Tubb WF			
1. Type of Well       X     Oil Well     Other					8. Well Name and No.			
2. Name of Operator ConocoPhillips Company					#52 9. API Well No.			
3a. Address 3b. Phone No. (include area code)   4001 Penbrook Street Odessa TX 79762 (432)368-1667					30-025-26033 10. Field and Pool, or Exploratory Area Warren; Blinebry-Tubb O&G			
4. Location of Well ( Footage, Sec., T., R., M., or Survey Description ) 2310' FSL & 330' FEL, Sec. 29, I-20-S, R-38-E, UL "I"								
2310' FSL & 330' FEL, Sec. 29, 1-20-S, H-38-E, UL "1" I - 29.20 - 38					11. County or Parish, State Lea			
		TO INDICATE	NATURE	F NOTICE. RI	NM EPORT. C	RO	THER DATA	
TYPE OF SUBMISSION	PPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION							
	Acidize	Deepen	<u></u>	Production (Start	/ Resume)		Water Shut-Off	
X Notice of Intent	Alter Casing	Fracture Tr	reat 🗍	Reclamation			Well Integrity	
Subsequent Report	Casing Repair	New Const	ruction	Recomplete			Other	
Final Abandonment Notice	Change Plans	Plug and A		Temporarily Abas	ndon			
	Convert to Injection	Plug Back		Water Disposal				
Attach the Bond under which the following completion of the inv	onomical to produce du	ovide the Bond No m results in a multi e filed only after a e to low produ	on file with BL iple completion of il requirements, ition. Reque	M/BIA. Required or recompletion in : including reclamat	subsequent n a new interva- ion, have been tempore	reports al, a F en con urily a	shall be filed within 30 days orm 3160-4 shall be filed once apleted, and the operator has abandon in order to	
Procedure attached:				• • •	<b>13242526</b>	V.	93031-7237567891077 Hill Alles Hobbs 150 61 81 41 91 CLIVIE	
							-+ 8t Tr 3h	
14. I hereby certify that the foregoin	ng is true and correct		Title					
Name (Printed/Typed) Title   Celeste G. Dale Regulatory Analyst								
Signature Juliste A Jale 10/31/2003								
	THIS SPACE	FORFEDERA	LORSTATE	OFFICE USE		••••••••••••••••••••••••••••••••••••••		
Approved by	<u> 6. 960.) .10F G. L</u>		Title	Petrolema IS	, ectacor	Date	10/31/03	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.								
Title 18 U.S.C. Section 1001, make fraudulent statements or representa-	s it a crime for any person kno fions as to any matter within its	wingly and willfu jurisdiction.	lly to make to a	ny department or a	gency of the	a Unit	ed States any false, fictitious or	
(Instructions on reverse) GW	W							

## ConocoPhillips Warren Unit #52 API # 30-025-26033-0000 Sec.29-T20S-R38E Lea County, New Mexico

## JUSTIFICATION

ConocoPhillips desires temporary abandonment approval in order to retain this well bore for evaluation of possible re-completion potential. This evaluation should be done in the next 12 to 18 months.

## PROPOSED TEMPORARY ABANDONEMENT PROCEDURE 6/20/2003:

- 1. MIRU pulling unit. ND wellhead, NU BOP
- 2. POOH with production equipment.
- 3. RIH with working tubing string, bit & scraper to  $\pm$  5770' just above perforations. POOH w/tubing, bit & scraper.
- 4. RIH w/ CIBP for 7", K55, 23 lb/ft casing, set 50' above top perforation at 5762' POOH.
- 5. Circulate inhibited fluid. POOH, LD tubing.
- 6. Pressure test casing to 500 psi for 30 min. Release pressure.
- Send chart to ConocoPhillips Regulatory Department (Kristy Ward and/or Celeste Dale) to finalize TA. Change status of well to TA. Temporarily Abandoned.
- 8. ND BOP, NU wellhead, RDMO.

P.03