Submit 3 copies to Appropriate District Office	Energy, Minerals and Natural Re			Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION P.O. Box 2088		WELL API NO. 30-025-34477	
DISTRICT II P.O. Box Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	1	5. Indicate Type of Lease STATE	FEE [
DISTRICT III  1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.	1 1 1 1
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.		7. Lease Name or Unit Agreement MONUMENT "1" STATE	Name	
1. Type of Well: OIL GAS WELL WELL	- OTHER			
Name of Operator     CHEVRON U	SA INC	8. Well No. 26		
Address of Operator 15 SMITH RO	DAD, MIDLAND, TX 79705	Pool Name or Wildcat     MONUMENT ABO, NORTH		NORTH
Well Location     Unit Letter;  Section1		H Line and 2276' ange 36-E NMI	_Feet From The <u>EAST</u> PM <u>LEA</u> 0	_Line
1002.4	10. Elevation (Show whether DF, RKB,	RT,GR, etc.) 3734' GL		
11. Check Ap	opropriate Box to Indicate Natu	ure of Notice, Report,	or Other Data	
NOTICE OF INTENTION TO:		BSEQUENT REPORT	OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	G 🔲
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPE	RATION PLUG AND ABAND	OONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT	T JOB	
OTHER: INTEN	T TO TA	OTHER:		
<ol> <li>Describe Proposed or Completed Oper proposed work) SEE RULE 1103.</li> </ol>	erations (Clearly state all pertinent de	etails, and give pertinent da	ites, including estimated date of	starting any
CHÉVRON U.S.A. INTENDS TO TEMPO	PRARILY ABANDON THE SUBJECT	WELL.		
THE INTENDED PROCEDURE AND WE	ELLBORE DIAGRAM IS ATTACHED	FOR YOUR APPROVAL.		
THE SUBJECT WELL HAS FUTURE UT	ILITY AND WOULD BE USED IN FL	JTURE EXPANSIONS.		
			12345031 123450 303 10111213450 101111213450 101111213450 101111213450 101111211400 1011112114000000000000000	020 27 25 25 25 25 25 25 25 25 25 25 25 25 25

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE MUSE CARE TITLE	Regulatory Specialist	DATE	10/30/2003
TYPE OR PRINT NAME Denise Leake		Telephone No.	915-687-7375

OC FIELD REPRESENTATIVE II/STAFF MANAGERNOV 1 0 2003

## Monument 1 State #26

API# 30-025-34477 2279' FSL & 2276' FEL S1, T19S, R36E, UNIT J MONUMENT ABO UNIT Lea County, New Mexico

## PROCEDURE TO TEMPORARILY ABANDON WELL:

Notify OCD/BLM 24 hrs prior to work commencing.

- 1. Verify anchors have been set & tested.
- 2. MIRU PU. ND WH. NU BOP.
- 3. Pull rods, pump and 2-7/8" tubing.
- 4. TIH w/ 4-3/4" bit, csg scraper on 2-7/8" WS. Make bit trip to 7300'. POH.
- 5. Set CIBP @ 7250' or within 75' of csg shoe (7313'). Dump 35' cmt on top of plug. (new PBTD 7215')
- 6. TIH w/2-7/8" WS & tag TOC (7215'). Circ csg w/corrosion inhibited pkr fluid. TOH.
- 7. Perform MIT (500 psi for 30 min). If test fails, contact Jerry Poole for further instructions.
- 8. ND BOP. NU WH. RD PU.
- 9. Clean and clear location.

Jerry Poole

Office phone: 432-687-7165 Cell phone: 432-556-0332

## **WELL DATA SHEET**

FIELD: Monument

WELL NAME: Monument 1 State #26

FORMATION: Abo

LOC: Unit J, 2279' FSL & 2276' FEL

TOWNSHIP: 19S RANGE: 36E

SEC: 1

COUNTY: Lea


GL: 3734'

KB to GL:

**CURRENT STATUS:** API NO: 30-025-34477

DF to GL:

REFNO: BS4913



8 5/8", 23#, WC-50 Csg Set @ 1483' w/450 sx cmt. Circulated to surface.

Tubing Detail (3/22/01) 234 jts 2-7/8" EUE 8rd L-80 tbg EOT landed @ 7526'

5 1/2", 15.5#, K55 Csg Set @ 7313' w/1000 sx cmt. Did not circulate. Est. TOC @ 1120'

Spot 500 gals 15% acid in open hole. RIH w/pkr and set @ 7259'. Acdz OH w/7000 gals 28% acid. 3/01: New tubing detail. Pulled pkr out of hole. OH Interval 7313-7468