

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

| | | |
|--|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. 30-025-35288 |
| 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 2. Name of Operator Echo Production, Inc. | | 6. State Oil & Gas Lease No. 26984 |
| 3. Address of Operator PO Box 1210, Graham, TX 76450 | | 7. Lease Name or Unit Agreement Name: James |
| 4. Well Location Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>east</u> line Section <u>21</u> Township <u>23S</u> Range <u>32E</u> NMPM County <u>Lea</u> | | 8. Well No. 1 |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3689 | | 9. Pool name or Wildcat Diamondtail Delaware, SW |

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

13 3/8" csg @ 629' cmt to surface. 8 5/8" csg @ 4874' cmt to surface. 5 1/2" csg @ 8710'. TOC 6308' perforations 7418-8512'. BP @ 7851'.

To P&A set CIBP @ 7380' w/ 4 sx cmt on top. Cut and pulled 5 1/2" csg @ 6200'. Spot 50 sx cmt plug @ 6250'. Tag top of plug @ 6137'. Spot 60 sx plug @ 49180'. Could not tag. Spot 100 sx plug @ 4930'. Tag @ 4715'. Spot 35 sx plug @ 1200'. Spot 35 sx 680'. Tag @ 569'. Set 15 sx plug 0-60'. Cut off casing and installed dry hole marker. Started P&A 10/20/03, Finished 10/31/03.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom Golden TITLE Operations Manager DATE 11/06/03

Type or print name Tom Golden Telephone No. 940-549-3292

(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE NOV 12 2003

Conditions of approval, if any:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.