(April 2004) BUREAU OF I BUREAU OF I	TED STATES IT OF THE INTERIOR AND MANAGEMENT AND REPORTS ON WELLS proposals to drill or to re-enter an m 3160-3 (APD) for such proposals.	FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007 5., Lease Serial No Fall C - 032233 (A) 6 If Indian, Allottee or Tribe Name	
	n 3160-3 (APD) for such proposals. 	7. If Unit or CA/Agreement, Name and/or No	
Type of Well X Oil Well Gas Well Other Name of Operator Occidental Permian Limited Partner		8 Well Name and No North Hobbs G/SA No. 625 Unit 9. API Well No	
 3a Address P.O. Box 4294, Houston, TX 77210- 4. Location of Well (Footage, Sec., T., R, M., or Survey I 		30-025-37213 10. Field and Pool, or Exploratory Area	
1755' FNL & 977' FWL, Sec. 29, Letter E, T-18-S, R-38-E (SHL)		Hobbs; Grayburg-San Andres 11 County or Parish, State Lea Co. NM	
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Alter Casing Fracture Treat Reclamat Casing Repair New Construction Recompleter	ete X Other <u>OAP and</u> rily Abandon <u>acid stimulate</u>	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection)

7/7/08 - 7/10/08:

MI x RU. ND WH x NU BOP. POOH with ESP production equipment. RIH with 4-3/4" bit on 2-7/8" tubing. Tag PBTD at 4835'. RU Schlumberger and perforate at 4142' - 4151', 4155' - 4158', and 4161' - 4165', 2 JSPF (38 holes). RIH with 5-1/2" PPI tool with 64' spacing. Set packer at 4226' and acidize 4231' - 4285' with 18 bbls 15% HCL. Set packer at 4136' and acidize 4142' - 4192' with 16 bbls 15% HCL. POOH with packer x RBIH with ESP equipment on 124 jts. 2-7/8" production tubing (tubing set at 4011', intake set at 4042'). ND BOP x NU WH. RD x MO x clean location. Turn well back over to production.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Mark Stephens	Tıtle	Regulato	ACOMPETER AND A RECORD
Mark Stephens	Date	8/4 ¹ /08	
THIS SPACE FOR FEDER	AL OR STATE	OFFICE US	E ALIG 2 A 2003
Approved by	. Title :	4. 4. 4. 5. F. 4.	Date
Conditions of approval, if any, are attached Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject I which would entitle the applicant to conduct operations thereon	nt or Office ease		BUREAU OF LAND MANAGEMENT
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for States any false, fictitious or fraudulent statements or representations as to any matter	any person known within its jurisdicti	ngly and willful ion	y to make to any department or agency of the Unite