

Form C-103 Submit 2 Copies To Appropriate District tate of New Mexico Office October 25, 2007 and Natural Resources District I WELL API NO. 1625 N French Dr., Hobbs, NM 88240 30-025-37943 District II OIL CONSERVATION DIVISION 1301 W Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE FEE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Javelina DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number 1. Type of Well: Oil Well Gas Well X Other 9. OGRID Number 2. Name of Operator 778 BP America Production Company 10. Pool name or Wildcat 3. Address of Operator Wildcat; Morrow P.O. Box 1089 Eunice, NM 88231 4. Well Location Unit Letter M: 430 feet from the South line and 950 feet from the West line Section 10 Township 22S Range 36E NMPM \_ 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3551' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING P AND A COMMENCE DRILLING OPNS.□ **CHANGE PLANS** TEMPORARILY ABANDON CASING/CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPL □ Location is ready for OCD inspection after P&A OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed. My BOA for Barry Price TITLE Operations Specialist DATE 8/12/08

IAME Barry C. Price E-MAIL: barry. price @bp. com PHONE: 575-394-1448 TYPE OR PRINT NAME Barry C. Price For State Use Only TITLE Compliance Officer

Conditions of Approval (if any):