Gas Well

Location of Well (Footage, Sec., T.,R.,M., or Survey Description)

determined that the site is ready for final inspection.)

Swab'd well down to SWD tank, SDON.

Swb'd well down to recover 49 BLW, weak shows.

Swb'd down to recover 44 BF w/ 10% oil show.

Swb'd down to recover 28 BF w/ 20% oil show. RD PU.

8-15-08: Swb'd down to recover 25 BLW + 8 BNW, small shows. SD for weekend.

Well shut down while evaluating further prospects

New Mexico Oil Conservation Division, District [

1625 N. French Drive Hobbs, NM 88246

OMB No. 1 Expires: Marci

Form 3160-5 (February 2005)

1. Type of Well

3a. Address

8-14-08:

8-18-08:

8-19-08·

(Instructions on page 2)

300 W, Louisiana Midland, TX 79701

T-8-S, R-37-E

Oil Well

2. Name of Operator H. L. Brown Operating, L.L.C

TYPE OF SUBMISSION

Notice of Intent

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

abandoned well. Use Form 3160-3 (APD) for such proposals.

Other

Acidize

Alter Casing

Casing Repair

Change Plans

Convert to Injection

SUBMIT IN TRIPLICATE - Other instructions on page 2.

FIGES AND PEPORTS ON WELLS ให้เร็จได้เกิก for proposals to drill or to re-enter an

3b. Phone No. (include area code)

(432) 688-3727

Deepen

Plug Back

Fracture Treat

New Construction

Plug and Abandon

5. Lease Serial No. NM 021097A 6. If Indian. Allottee or Tribe Name 7. If Unit of CA/Agreeme 8. Well Name and No. Federal H No.2 API Well No. 30-041-20934 10. Field and Pool or Exploratory Area **Bluitt Wolfcamp** 11. Country or Parish, State Roosevelt County, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION Water Shut-Off Production (Start/Resume) Well Integrity Reclamation Recomplete Other Temporarily Abandon Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has. POH w/ tbg and pkr . Set CIBP @ 8425', w/ 35' cement on top. New PBTD @ 8390'. Perfed 8143-52' 2spf w/ csg gun. TIH w/ tbg and pkr to 8050'. Acidized w/ 1500 gals 15% NEFE w/ 25 ball sealers. Pressure went on vacuum after 500 gals acid in perfs. Swb'd dry, SDON. 74 BLWTR.

14. I hereby certify that the foregoing is true and correct.  Name (Printed/Typed)	
Carlton Wheeler Carton Wheeler	Title Operations Manager
Signature ,	Date 08/28/2008
ACCEPTED FOR RECORDS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by SEP 2008  Conditions of approval Trahy, are attached. Approval of this notice does not warrant or conditions.	Title'; Date
Conditions of approval. If any, are attached. Approval of this notice does not warrant or chat the applicant holds legal or equitable title to those rights in the subject lease which we	pertify Office
entitle the applicant to conduct operations thereon.	<u> </u>
Title 18 U.S.C. Section 1000 and Title 43 D.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements of representations as to any matter within its jurisdiction.	