Form 3160-5 (August 2007)

OCD-HOBBS

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM AI	PPRO	VED
OMB No	1004-	0137
Evniror: In	dv 31	201

Expires: July 31, 2010

5. Lease Serial No.
LC060825B

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

abandoned well.	Use Form 3160-3 (A	(PD) for such proposa	is.		
SUBMIT IN TRIPLICATE – Other instructions on page 2.		7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well				†	
Oil Well Gas Well Other		8. Well Name and No. EVA BLINEBRY B #5			
2. Name of Operator RANGE OPERATING NEW MEXIC	O, INC.			9. API Well No 30-025-38574	-
Ba. Address 100 THROCKMORTON STREET, SUITE 1200 FORT WORTH, TEXAS 76102		3b. Phone No. (include area co (817) 869-4145	ode)	10. Field and Pool or BLINEBRY, TUBB	• •
1. Location of Well (Footage, Sec., T., I	R.,M., or Survey Description	1)		11. Country or Parish,	State
JNIT F, SEC 34, T23E, R37E				LEA	
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOTIO	CE, REPORT OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
✓ Notice of Intent	Acidıze	Deepen	Prod	uction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Recl	amation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Reco	mplete	Other
	Change Plans	Plug and Abandon	Tem:	porarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back		r Disposal	
3 Describe Proposed or Completed Op	peration. Clearly state all pe	rtinent details, including estimate	d starting da	te of any proposed wor	k and approximate duration thereof. If

the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

RANGE OPERATING NEW MEXICO, INC. PLANS TO MOVE PATTERSON RÍG 63 OFF THE SUBJECT WELL. A SMALLER RIG WILL BE MOVED ON TO LOCATION AS SOON AS AVAILABLE.

A WELL CONTROL SPECIALIST IS ON SITE. THE WELL IS SHUT IN AND THE BOP WILL REMAIN ON THE WELL.



JUN 1 3 2003 HOBBS OCD

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		
LINDA L. BROWN	Title Regulatory Analyst	
Signature Anda Proun	Date 04/30/2008	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		USE APPROVED
Approved by		
2**************************************	Title	Date APR 3 0 2008
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon	or certify n would Office	WESLEY W. INGRAM
Title 18 U.S C. Section 1001 and Title 43 U S C. Section 1212, make it a crime for an fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	y person knowingly and willfully to maketion	te to any department of agency of the United States any fals
(Instructions on page 2)		W 1

Eva Blinebry B #5 Range Operating New Mexico, Inc. April 30, 2008 Conditions of Approval

- 1. BOP will be properly supported to enable removal of rig well control specialist is onsite and is developing plans for BOP support and rig removal.
- 2. Flow tree will be removed, reinstalled and properly supported to enable long term bleed down of the well.
- 3. Temporary flow lines will be installed to bleed well. Please submit routing for flow lines as a temporary ROW may be required if they cross lease boundaries.
- 4. Continue to monitor H2S concentrations.
- 5. Well control specialist to remain on site until threat has been eliminated.

WWI 043008