Submit 3 Copies To Appropriate District Sta	te of New Mexico	Form C-103
Office District 1 Energy, Mir	nerals and Natural Resources	June 19, 2008
1625 N. French Dr., Floods, NM 88240		WELL API NO. 30-005-00852
District II 1301 W. Grand Ave., Artesia, SNE8 212-6 2008 CONS	SERVATION DIVISION	5. Indicate Type of Lease
	South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	nta Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Org Salar Folking	,	303375
87505 CANDON NOTICES AND REPORT	ATC ON WELLC	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORT (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT	O DEEPEN OR PLUG BACK TO A	Rock Queen Unit
PROPOSALS.)		8. Well Number 61
1. Type of Well: Oil Well X Gas Well Ott	her	01
2. Name of Operator CELERO ENERGY II, LP	\checkmark	9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601	*	10. Pool name or Wildcat
Midland, TX 79701	•	Caprock Queen
4. Well Location		- Caproon (according to the caproon of the caproon
	om the South line and 198	0 feet from the West line
	hip 13S Range 31E	NMPM County Chaves
	how whether DR, RKB, RT, GR, etc.,	
4397' GR	now whether DR, RRB, R1, OR, etc.,	
The state of the s		
12. Check Appropriate Box	to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO	. QUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABA		
TEMPORARILY ABANDON CHANGE PLAN		
PULL OR ALTER CASING MULTIPLE COM		
DOWNHOLE COMMINGLE	" E B ONOMO O ENTEN	. 005
DOWN IOLE COMMINGEE	<u> </u>	
OTHER:	OTHER: Return v	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1	Clearly state all pertinent details, an	
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion.	Clearly state all pertinent details, an	d give pertinent dates, including estimated date
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 	Clearly state all pertinent details, an	d give pertinent dates, including estimated date
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 	Clearly state all pertinent details, an 103. For Multiple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl 	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to see the service of the	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to say gals 80-20 mixture of 7.5% NEFE acid and toluene. 	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to see the service of the	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
of starting any proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production.	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing 	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
of starting any proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production.	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
of starting any proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production.	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
of starting any proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production.	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
of starting any proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production.	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
of starting any proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production.	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. 	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidi, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date:	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. 	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date:	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene, load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date:	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date:	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene, load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date:	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity e and belief. DATE 9/24/08
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date: I hereby certify that the information above is true and of SIGNATURE SIGNATURE SIGNATURE SIGNATURE SEE RULE 1 OF 18 AUGUST OF	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (Rig Release Date: Complete to the best of my knowledg TITLE Regulatory Analyst E-mail address: LHunt@celeroen	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity e and belief. DATE 9/24/08 nergy.com PHONE: (432)686-1883
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date: Spud Date: Type or print name Lisa Hunt For State Use Only	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (Complete to the best of my knowledged) TITLE Regulatory Analyst E-mail address: LHunt@celeroen	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity e and belief. DATE 9/24/08 nergy.com PHONE: (432)686-1883
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 or recompletion. Returned this abandoned producer to production. 7/24/08-8/11/08 MIRU well service rig. Repaired wellhead and repl TD @ 3067'. Pressure tested casing from 2881' to s gals 80-20 mixture of 7.5% NEFE acid and toluene load back. Ran 2 3/8" 4.7# J-55 production tubing pumping system. Returned well to production. NOTE: This well last produced 8/1996. Spud Date: I hereby certify that the information above is true and c SIGNATURE SIGNATURE Type or print name Lisa Hunt	Clearly state all pertinent details, an 103. For Multiple Completions: At laced top 4 joints of 4 1/2" casing. Courface to 500 psi, tested OK. Acidit, and 1000# rock salt in three stages and TAC. Set TAC @ 2988', EOT (Rig Release Date: Complete to the best of my knowledg TITLE Regulatory Analyst E-mail address: LHunt@celeroen	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CO, milled out and recovered fish. CO well to zed Queen interval (3045' - 3067') w/ 2500 @ 4.1 BPM and 1080 psi avg STP. Swabbed @ 2992'. Installed progressive cavity e and belief. DATE 9/24/08 nergy.com PHONE: (432)686-1883

CELERO ENERGY

DATE: Sept. 24, 2007 FIELD: Caprock BY: **GSA** LEASE/UNIT: Rock Queen WELL: 61 COUNTY: Chaves STATE: New Mexico Location: 1980' FSL & 1980' FWL, Sec 25k, T13S, R31ECM KB = 4397'SPUD: 5/55 COMP: 5/55 GL = CURRENT STATUS: T.A.Producer API = 30-005-00852Original Well Name: W. M. Tulk #2 11" 7-5/8" 26.4# @ 331' cmt'd. w/ 250 sx. TOC @ surface (calc). PRE-WORKDUER 6 3/4" TOC 2400' +/- (calc) 4-1/2" 9.5# @ 3045' cmt'd. w/ 75 sx (DNC) Top of Queen @ 3045': Queen Open Hole: 3045' - 3067' (5-55) PBTD - 3067' TD - 3067' 9/24/2008 **RQU #61**

CELERO ENERGY

DATE: Aug. 20, 2008 FIELD: Caprock BY: **JEA** LEASE/UNIT: Rock Queen WELL: 61 **COUNTY:** Chaves STATE: New Mexico Location: 1980' FSL & 1980' FWL, Sec 25k, T13S, R31ECM KB = 4397'SPUD: 5/55 COMP: 5/55 GL = CURRENT STATUS: T.A.Producer API = 30-005-00852Original Well Name: W. M. Tulk #2 11" 7-5/8" 26.4# @ 331" cmt'd. w/ 250 sx. TOC @ surface (calc). POST-WORKDUER 2 3/8" 4.7# J-55 production tubing w/ TAC @ 2988', EOT @ 2992'. Installed PC pumping system 6 3/4" TOC 2400' +/- (calc) 4-1/2" 9.5# @ 3045' cmt'd. w/ 75 sx (DNC) Top of Queen @ 3045': Queen Open Hole: 3045' - 3067' (5-55) PBTD - 3067' TD - 3067 9/24/2008 Copy of RQU #61