			e Gil Cons		Second V		
	Form 3160-5 . (April2004)	UNITEDSTAT	ES 1623 F	A LIPTVE	FORMAPPROVED		
		DEPARTMENT OF TH	e interior, My		OM B No 1004-0137 Expires March 31, 2007		
	•	BUREAU OF LAND MA		010520	8. Lease Serial No.		
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to repender any abandoned well. Use Form 3160-3 (APD) for such proposals.						
	SUBMIT IN TR	IPLICATE - Other ins	tructions on reve	rse side.	7. If Unit or CA/Agreement, Name and/or No. $M - 7/0 \ge 5 \times$		
	1. Type of Well	1. Type of Well Gas Well Other					
•				······	8. Well Name and No. Rock Queen Unit 35		
	2. NameofOperator	. Name of Operator					
	3a Address		de area code)	30-005-00872 🗸			
	400 W. Illinois, Ste. 1601	1 Midland TX 79701	883	10. Field and Pool, or Exploratory Area			
	4. Location of Well (Footage, Se	ec, T., R., M, or Survey Desc	ription)		Caprock Queen		
. * [*]	⊂660 North 660 East UL: A; Sec: 26, T: 13S, F	R: 31E .			11. County or Parish, State Chaves		
~	12. CHECK A	12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
	TYPE OF SUBMISSION	TYPE OF ACTION					
		X Acıdize	Deepen	X Production (St	art/Resume) Water Shut-Off		
	Noticeof Intent		FractureTreat	Reclamation	Well Integrity		
	X Subsequent Report	Casing Repair	New Construction		Other		
	·	Change Plans	Plug and Abandon	· · ·	bandon		
	Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa	l		
	Attach the Bond under which following completion of the ir testing has been completed F determined that the site is read Returned this abandone	true vertical depths of all pertinent markers and zones. sired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once mation, have been completed, and the operator has					
8/26/08-9/2/08 TOOH w/rods, pump, and 2 3/8" production tubing. CO/DO well to new TD @ 3093'. Pressure tested 5 2923', tested good. Logged well w/ GR/CCL/CN log. Acidized Queen interval (3055' - 3093') w/ 500 gal t gal 80/20 mixture of 7.5% NEFE acid and toluene, and 1000 # rock salt in three stages @ 4 BPM and 11 STP. Swabbed load back. Ran 2 7/8" 6.5# J-55 production tubing and TAC. Set TAC @ 3021', EOT @ Installed progressive cavity pumping system. Returned well to production.							
	NOTE: This well last p	roduced 2/1999.					
	14 I hereby certify that the fore	egoing is true and correct					
	Name <i>(Printed/Typed)</i> Lisa Hunt		Title	Title Regulatory Analyst			
	/						
		Hunt	Date	09/26/2008	Kæ		
		ACCEPTED FTHIS SPACE FOR FEDERAL OR STATE OFFICE USE					
	Approved by //S/DA Conditions of approval, if app are certify that the applicant holds leg which would entitle the applican Title 18 U S C. Section 1001 and T States any false, fict thous of trad	t to conduct operations thereo	ce does not warrant or hts in the subject lease 1.	Subject To Production Production	or Record Only! Approval Returning Well To Continuous And Keeping Well On Continuous Or Plugging Well With An lugging Program!		
	(Instructions on page 2)			₹			

1

• • • • • • • • • •

. .

FIELD: LEASE/UNIT: COUNTY:	Caprock Rock Queen Chaves	DATE: Sept. 26, 2007 BY: GSA WELL: 35 STÀTE: New Mexico	
Location: 660' FNL & SPUD: 5/55 COMP CURRENT STATUS Original Well Name:	S: Producer	KB = 4412' GL = API = 30-005-00872	<u></u>
	8-5/8" 24# @ 305' cmt'd. w/ 140 sx	PRE - WORKOVER	
	2 7/8" tbg (97 jts) @ 3015'	Υ	
	TOC ?	:	
	 5-1/2" 14# @ 3053' cmt'd. w/ 125 sx (DNC) Top of Queen @ 3055': Queen Open Hole: 3053' - 3065' (2000) 	5-55)	

ł

__ __

. (***** . .

1

