

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

WELL API NO. 30-025-22788
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Henry
8. Well Number 4
9. OGRID Number 018687
10. Pool name or Wildcat LM - SR- Queen - GRB
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3019 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Intrepid Operating LTD, Co.

3. Address of Operator
P.O. Box 3197, Hobbs, NM 88241

4. Well Location
Unit Letter K : 1980 feet from the South line and 1980 feet from the West line
Section 26 Township 25S Range 37E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Return to Production <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Test anchors. TIH with 2 3/8" tubing. Clean out 4.5" casing to 3400'.
2. Acid stimulate 3100 to 3232 w/2000g 15% NEFE HCL acid.
3. RIH w/production equipment.
4. Well shut down waiting on electric meter.

Rig Up Date: 10/06/2008
Rig Down Date: 10/09/2008

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Gilbert TITLE Owner/Operator DATE 10/09/2008

Type or print name Robert Gilbert E-mail address: robsky73@mywdo.com Telephone No. 505-390-0690
(This space for State use)

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE OCT 10 2008
Conditions of approval, if any: