| Submit 3 Copies To Appropriate District Office District I Energy, Minerals and Natural Resources | Form C-103 |
|--|--|
| DISTRICT TO THE PARTY OF THE PA | Revised March 25, 1999 |
| 1625 N. French Dr , Hobbs, NM 88240 | WELL API NO. |
| District II 811 South First, Artesian 1820 9 2008 OIL CONSERVATION DIVISION | 30-025-27992 |
| Lightief III | 5. Indicate Type of Lease |
| 1000 Rio Brazos Rd. Aztec NM-87410 District IV. Santa Fe, NM 87505 | STATE FEE |
| 1220 S. St. Francis D. Sagra C. NM. | 6. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name: |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) | Coquina State |
| 1. Type of Well: Oil Well Gas Well Other | |
| 2. Name of Operator | 8. Well No. |
| 1 | 8. Well No. |
| Marks and Garner Production Ltd. Co.3. Address of Operator | 9. Pool name or Wildcat |
| | 1 |
| P.O. Box 1089, Hobbs, NM 88241 | San Simon; Yates North (Assoc) |
| 4. Well Location | |
| Unit Letter H, 1980 feet from the North line and 660 feet from the East line | |
| Section 19 Township 21S Range 35E | NMPM Lea County |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.) | |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | |
| | SSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR | |
| TEMPORARILY ABANDON | PLUG AND ABANDONMENT X |
| PULL OR ALTER CASING | ND |
| OTHER: OTHER: | П |
| 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 8/28/08 to 9/30/08 Approved for plugging of well bore only. | |
| 8/28/08 to 9/30/08 | and the standing retained pending received |
| Set CIBP @ 3600' + and cap with 35' cement. Tag cement on CIBP @ 3562'. | of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under |
| Circulate hole with salt gel. Spot 25 sx plug at base of salt @ 1620'. | Forms, www.cmnrd.state.nm.us oed. |
| Tag $@ \pm 1515$ '. Pull tbg. to 500'. Pump 50 sx cement. Circulate cement to surface. Cut off wellhead; weld on dry hole marker 3' below surface. Clean location and remediate. | |
| | |
| | |
| I hereby certify that the information above is true and complete to the best of my knowled | dge and belief. |
| SIGNATURE Ochlie M Kely TITLE AGENT | DATE10/07/08 |
| Type or print name/ Quinton Welborn Telephone No. | 575-393-9358 |
| (This space for State use) | TE 11 /STAFF MANCACES |
| APPPROVED BY TITLE | 0CT 14 2008 |
| Conditions of approval, if any | |

Coquina State !

