

Submit 3 Copies to Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-08101
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> FED <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Young Unit
8. Well Number 21
9. OGRID Number 19086
10. Pool name or Wildcat Penrose

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ Injection

2. Name of Operator
State of NM, Formerly Sierra Blanca Oper.

3. Address of Operator
1625 N. French Dr., Hobbs, NM 88240

4. Well Location

Unit Letter J : 1980 feet from the South line and 1980 feet from the East line
Section 20 Township 18s Range 32e NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU Plugging equipment, pull injection equipment if any in hole.
2. Set CIBP @ 3964' Circ. Hole w/ MLF, Spot 25 sx. Cmt. on top of CIBP.
3. Spot 25 sx. Cmt. @ 2500', BOS
4. Perforate csg. @ 1069' and squeeze with 40 sx. Cmt., WOC and tag.
5. Perf. @ 350' and circulate cmt. to surface inside and out.
6. Cut off well head, install dry hole marker and clean location.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Cary W. Hill

OC FIELD REPRESENTATIVE II/STAFF MANAGER
TITLE

DATE

OCT 15 2008

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

Cary W. Hill

OC FIELD REPRESENTATIVE II/STAFF MANAGER
TITLE

DATE

OCT 15 2008

Conditions of Approval (if any):

PLUGGING & ABANDONMENT WORKSHEET (2 STRING CSNG)

OPERATOR SIERRA BLANCA 30-025-08101
 LEASENAME Young UNIT

SECT 20 TWN 18S RNG 32E
 FROM 1980 N/S 1980 E/W
 TD: 4068 FORMATION @ TD
 PBDT: FORMATION @ PBDT

4L-J

19086

Q1

8 5/8"
 @ 1019
 TOC CIRC.

Top Perf.
 4014

5 1/2"
 @ 4066
 TOC ?

TD 4068'

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	<u>8 5/8</u>	<u>1019</u>	<u>CIRC.</u>		
INTMED 1					
INTMED 2					
PROD	<u>5 1/2</u>	<u>4066</u>	<u>?</u>		
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS		-
INTMED 2			OPENHOLE		-
PROD					

*REQUIRED PLUGS DISTRICT I

KUSTLER (ANYTD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDREW	
CANTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRISBY CANYON	
BONE SPRING	
OLORIETA	
BLINDBRY	
TUBE	
DRINKARD	
ABO	
WC	
PENNY	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVOREAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350'-5450'
PLUG #3	CIBP/35'		4800'
PLUG #4	CIBP	25 SXS	4800'
PLUG #5	STUB	50 SXS	3600'-3700'
PLUG #6	REINR SQZ	200 SXS	400'
PLUG #7	SURF	10 SXS	0-10'
PLUG #1	CIBP	25sx	3964'
PLUG #2	BOS	25sx	2500'
PLUG #3	TOSTShoe	40sx	Perf. 1069'
PLUG #4	Perf	350'	Water 30sx.
PLUG #5	SURF	10sx	60'
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			

CIRC.