Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natural Resources		WELL API NO.	Revised May 08, 2003
1625 N. French Dr., Hobbs, NM 88240			30-025-33618	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FEE	
District IV	IV Santa Fe, NW 67505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-2209-16	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			North Monument G/SA Unit	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well ☐ Gas Well ☒ Other Water Supply Well			624 (WSW)	
			9. OGRID Number	
Name of Operator Amerada Hess Corporation			000495	
3. Address of Operator			10. Pool name or Wildcat	
P.O. Box 840 Seminole, Texas 79360			San Andres WSW	
4. Well Location				•
	4990 C C II North	1: 6	60 feet fro	m the East line
Unit Letter H :	1830 feet from the North	line and 6	60 feet fro	m the <u>Last</u> the
Section 20	Township 19S Ra	ange 37E	NMPM	County Lea
	11. Elevation (Show whether DR,			
建造成的种类等等的发生的	3667' GR			
	Appropriate Box to Indicate N	ature of Notice,	Report or Other	Data
NOTICE OF IN			SEQUENT RE	_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	к ⊔	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	ND 🗆	ABANDONNEN
OTHER:	. 🗀	OTHER: Temp	oorarily Abandon we	ell 🗓
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed we or recompletion.	ork). SEE RULE 1103. For Multip	le Completions: At	tach wellbore diagr	ram of proposed completion
10/27/2003 thru 10/29/2003				
@ 3986'. TIH w/ side door of scale out w/tools. TIH w/9 5 Grayburg is @ 4025'. TOH laying down w/tbg & SN. Ro	g unit. Install a 10" 900 BOP. RU Ja overshot and 128 jts of 2 7/8" tbg. T 5/8" CIBP & 130 jts of 2 7/8" tbg. Se w/tbg & setting tool. TIH w/2 7/8" S emoved 10" 900 BOP & installed we o 560 psi & pressure remained cons	FOH w/gauge ring, to et CIBP @ 4058' and SN & 130 jts of 2 7/8 ellhead flange. Finis	bg and overshot. B d pulled out of plug " tbg. Circulated 30 shed filling up 9 5/8'	rought small amount of w/setting tool. Bottom of 00 bbls of pkr fluid. TOH csg w/35 bbls of pkr fluid, location. Well TA'd.
Attachment: chart	This Approval of Abandonment Expi	f Temporary ires/	11/18/08	123456 > 03 03 03 03 03 03 03 03 03 03 03 03 03
I hereby certify that the information	above is true and complete to the b	est of my knowledg	e and belief.	12 0 3
THE AND THE	TY O THE S	Senior Advisor		DATE 11/14/2003
SIGNATURE (1000)	11 CE 3	eriioi Advisoi		DATE: 01/14/2005
Type or print name Carol J. Moo	ore cmoore@he	ss.com	Telep	hone No. (432)758-6738
(This space for State use)				
APPPROVED BY LOUIS OC FIELD REPRESENTATIVE II/STAFF MANAGER NOV 18 2003				
Conditions of approval, if any:				

