

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLIC OF CT 2 0 2008

## OIL CONSERVATION DIVISION

oil conservation division	
DISTRICT I 1220 South St. Francis Dr. 1625 N Frence District 120 South St. Francis Dr. Sonta Fe NIM 87505	WELL API NO. 30-025-07464
DISTRICT II Santa Fe, NM 87505	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	T. Land Manager II.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 30
1. Type of Well:	8. Well No. 121
Oil Well X Gas Well Other	V
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.  3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	110000 (0,0.1)
4. Well Location	/
Unit Letter E : 2310 Feet From The North 330 Feet From The West Line	
Section 30 Township 18-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.)	
3650' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
Charles The Market Programme Charles The Color Date	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
OTHER: OAP/Acid treat X OTHER.	
On the first treat	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
proposed word, see	
1. Kill well. POOH w/production equipment.	
2. Clean out to PBTD @4312'. 3. Perforate well.	
4. Set packer and acid treat well w/15% HCL Pad acid w/gelled rock salt block.	
<ul><li>5. Perform scale squeeze.</li><li>6. Run back in hole w/production equipment and return well to production.</li></ul>	
6. Run back in note w/production equipment and return wen to production.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	hat any pit or below-grade tank has been/will be
constructed or	
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	OCD-approved
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative	Associate DATE 10/14/2008
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy johnson@oxy.com	Associate DATE 10/14/2008  TELEPHONE NO. 806-592-6280
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com  For State Use Only	Associate DATE 10/14/2008  TELEPHONE NO. 806-592-6280  M ENGINEER 0 C 2 1 2008
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	Associate DATE 10/14/2008  TELEPHONE NO. 806-592-6280