Submit 3 Copies To Appropriate District Office State of	New Mexico Form C-103
District I Energy, Minerals	and Natural Resources May 27, 2004
1625 N French Dr. Houns NM 88240	WELL API NO.
District II 1301 W Grand Ave., Artesia, NM 88210 OIL CONSERV	/ATION DIVISION 30-025-20279
District III 1220 Court	St. Francis Dr. 5. Indicate Type of Lease STATE FEE FEE
1000 Rio Brazos Rd , Aztec, NO 7412 7 2008 Santa Fo	e, NM 87505 6. State Oil & Gas Lease No.
District IV 1220 S. St. Grances Dr. Santa Fe NM 87505	o. State on & Gas Lease No.
	NAME I C
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEE	<u> </u>
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FOR	M C-101) FOR SUCH
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	V
2. Name of Operator	9. OGRID Number 8041
Forest Oil Corporation 3. Address of Operator	10. Pool name or Wildcat
707 17 th Street, Suite 3600, Denver, Colorado	Maljamar Grayburg San Andres
	Wanjamar Orayourg San Andres
4. Well Location	
	ine and South feet and 660 from the East line
Section 8 Township 17S	Range 32E NMPM County Lea
- TO NOTE	nether DR, RKB, RT, GR, etc.)
Pit or Below-grade Tank Application ☐ or Closure ☐	R
	rest fresh water well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Vo	lumebbls; Construction Material
12. Check Appropriate Box to In	dicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO	OUDOFOLIENT DEDOOT OF
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	☐ REMEDIAL WORK ☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS	□ REMEDIAL WORK □ ALTERING CASING □ □ COMMENCE DRILLING OPNS. □ P AND A ☒
PERFORM REMEDIAL WORK PLUG AND ABANDON	□ REMEDIAL WORK □ ALTERING CASING □ □ COMMENCE DRILLING OPNS.□ P AND A □ □ CASING/CEMENT JQB Approved for plugging of well bore only.
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON TEMPORARILY ABANDON ☐ CHANGE PLANS PULL OR ALTER CASING ☐ MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB Approved for plugging of well bore only. Lightlity under bond is retained pending receipt
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLOTHER:	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLOTHER:	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLOTHER: 13. Describe proposed or completed operations. (Clearly	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLOTHER: 13. Describe proposed or completed operations. (Clearly	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under state all pertinent details, and given the province of the
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. F	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under state all pertinent details, and given the province of the
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion.	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PICK.	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER.	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT CN FLUID. SPOT 25 SX CMT © 2165.
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. Right in the complex person of the complex persons.	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under for Multiple Completions: Attach wellbore diagram of proposed completion WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT EN FLUID. SPOT 25 SX CMT @ 2165. EH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC.
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under for Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT IN FLUID. SPOT 25 SX CMT @ 2165. ON PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. O BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT ON FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. O BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN UG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT ON FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT ON FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. O BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280°. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023°. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION.	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under for Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT CN FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280°. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023°. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION.	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under state all pertinent details, and give the provider of the page under for Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT ON FLUID. SPOT 25 SX CMT 2165. OH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. OBOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION. I hereby certify that the information above is true and complete grade tank has been/will be constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the constructed or closed according to NMOCD and the property of the property of the constructed or closed according to NMOCD and the property of the property	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under for Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN LUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT CN FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION IN THE COMPLETE	REMEDIAL WORK
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION IN THE COMPLETE	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOR Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion WELL HEAD. NU BOP SDFN CUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT CN FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF et to the best of my knowledge and belief. I further certify that any pit or below-guidelines , a general permit or an (attached) alternative OCD-approved plan.
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PL@3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. R 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION Thereby certify that the information above is true and completed grade tank has been/will be constructed or closed according to NMOCD and SIGNATURE. Type or print name Cindy Bush E-mail address.	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under for Multiple Completions: Attach wellbore diagram of proposed completion OWELL HEAD. NU BOP SDFN CUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT in Fluid. Spot 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF Let to the best of my knowledge and belief. I further certify that any pit or below-guidelines, a general permit or an (attached) alternative OCD-approved plan. EITLE Sr. Regulatory Tech Telephone No. 303-812-1554
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PI @3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. RI 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH NI CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION IN THE COMPLETE	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under for Multiple Completions: Attach wellbore diagram of proposed completion OWELL HEAD. NU BOP SDFN CUG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT in Fluid. Spot 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF Let to the best of my knowledge and belief. I further certify that any pit or below-guidelines, a general permit or an (attached) alternative OCD-approved plan. EITLE Sr. Regulatory Tech Telephone No. 303-812-1554
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PL@3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. R. 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH N. CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION Thereby certify that the information above is true and complet grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed acco	REMEDIAL WORK COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JO Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion O WELL HEAD. NU BOP SDFN UG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT IN FLUID. SPOT 25 SX CMT @ 2165. CH W/ PACKER AND SET 2 945'. SQZ 40 SX CMT SDFN. WOC. D BOP. RIH W/ WIRELINE AND PERF. CSG @ 347'. NU SWEDGE ON AND UP BACK SIDE TO SURF CUT OFF WELL HEAD AND WELD ON. MOVE OFF The to the best of my knowledge and belief. I further certify that any pit or below-guidelines, a general permit or an (attached) alternative OCD-approved plan. TITLE Sr. Regulatory Tech DATE 10-20-08 St. cabush@forestoil.com Telephone No. 303-812-1554
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTHER: 13. Describe proposed or completed operations. (Clearly of starting any proposed work). SEE RULE 1103. For recompletion. 10-9-08 — MIRU RIG AND CEMENTING EQUIPMENT. NI 10-13-08 — PICK UP WORK STRING. RIH W/TBG TAG PL@3704-3463. POH TO 2280'. CIRC HOLE W/MUD LAIDE 10-14-08 — TAG PLUG 2 2010. SD FOR WEATHER. 10-15-08 — RIG UP WIRELINE. PERF 5 ½ CSG. @ 1100. R. 10-16-08 — RIH W/TBG AND TAG PLUG @ 1023'. POH N. CSG ESTABLISH CIRC. SQUZ 110 SX CMT DOWN CSG ON DRY HOLE MARKER. RIG DOWN CLEAN LOCATION Thereby certify that the information above is true and complet grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed acco	REMEDIAL WORK COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOAPHOVE of Plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under or Multiple Completions: Attach wellbore diagram of proposed completion WELL HEAD. NU BOP SDFN UG @ 3704' CIRC HOLE W/MUD LAIDEN FLUID. SPOT 25 SX CMT on Fluid