



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Environment"

05-Nov-08

HANSON OPERATING CO INC

PO BOX 1515

ROSWELL NM 88202

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


INSPECTION DETAIL SECTION

THELMA No.001Y				K-7-9S-30E	30-005-21039-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/05/2008	Plugged Well Surface Restor	Maxey Brown	Yes	No	2/8/2009	iMGB0831044390
Comments on Inspection:		DO NOT RELEASE (RULE 202), NEED TO REMOVE 2 TANKS ON NE CORNER OF LOCATION, ALSO, REMOVE EXPOSED ELECTRICAL WIRING FROM S SIDE OF LOCATION, AND SHORT PIECE OF SUCKER ROD 10 FT N OF WELLHEAD. YELLOW PLASTIC ANCHOR MARKER FROM NW CORNER OF LOCATION NEEDS REMOVAL. THIS IS 1ST LETTER OF NON-COMPLIANCE.				

PRESLER LAKE No.002				L-7-9S-30E	30-005-21108-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/05/2008	Routine/Periodic	Maxey Brown	Yes	No	2/8/2009	iMGB0831043388
Comments on Inspection:		Well Sign (Rule 103), API # not found. API # required on sign. Surplus equipment needs removal from SW corner of location, (Rule 114). This is 1st Letter of non-compliance. JRH				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




Hobbs OCD District Office

COMPLIANCE OFFICER

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER
017H15554612
\$0.42⁰
11/05/2008
Mailed From 88240
US POSTAGE

HANSON OPERATING CO INC
PO BOX 1515
ROSWELL, NM 88202