Submit 3 Gener Torship opring District Office State of New Mexicon		
District 17 Page 2017 Energy, Minerals and Natura	WELL API NO.	
District II NOV 12 2008 OIL CONSERVATION D	30-025-06605	
	. 5. Indicate Type of Lease	
1000 Rt Bh fos Resided NM 875 100 Santa Fe, NM 875	SIATE LI TEE LE	
District V 1220 S. St. Francis Dr., Santa Fe, NM	NA	
87505	7. Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	BACK TO A Northeast Drinkard Unit	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 723	
2. Name of Operator Apache Corporation	9. OGRID Number 00873	
3. Address of Operator 6120 S Yale Ave, Suite 1500	10. Pool name or Wildcat	
Tulsa, OK 74136-4224	Eunice; Blinebry-Tubb-Drinkard, N	
4. Well Location		
Unit Letter M: 330 feet from the South	line and 990 feet from the West line	
	ge 37E NMPM County Lea	
11. Elevation (Show whether DR, F	RKB, RT, GR, etc.)	
3445' DF		
12. Check Appropriate Box to Indicate Nat	ture of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
	REMEDIAL WORK ALTERING CASING	
	COMMENCE DRILLING OPNS. P AND A	
	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE		
	OTHER: Re-Completion Procedure	
13. Describe proposed or completed operations. (Clearly state all pe of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.	rtinent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion	
08/12 - 08/13/08 TAG PBTD @ 7465'. RAN CNL/GR/CCL LOGS F	OR ENGINEER EVALUATION	
08/14/08 PERF DRINKARD @ 6482-86, 6498-6502, 6535-39, 6602	-10' 2 JSPF	
08/14/08 ACID DRINKARD W/ 3000 GALS 15% HCl	0/40 CAND	
	08/18/08 FRAC DRINKARD W/ 40K GALS PAD AND 52K LBS 20/40 SAND 08/19/08 PERF TUBB @ 6052-56, 6106-12, 6162-68, 6228-34' 2 JSPF. SET RBP @ 6290'.	
08/20/08 ACID TUBB W/ 3000 GALS 15% HCl		
00,20,00 11010 1022 2000 01122 10.0	PF. SET RBP (#) 6290.	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S	AND	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCI 6/40 SAND	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 15% 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 5000'.	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND @ 5910'. RIH W/ PROD TBG TO 6730'.	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND @ 5910'. RIH W/ PROD TBG TO 6730'. JNIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 15% 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 5000'.	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND @ 5910'. RIH W/ PROD TBG TO 6730'. JNIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP (08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND @ 5910'. RIH W/ PROD TBG TO 6730'. UNIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND @ 5910'. RIH W/ PROD TBG TO 6730'. UNIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD Spud Date: Rig Release Date	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCI 9/40 SAND 19/5910'. RIH W/ PROD TBG TO 6730'. INIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP (08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCI 9/40 SAND 19/5910'. RIH W/ PROD TBG TO 6730'. INIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD Spud Date: Rig Release Date	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCI 9/40 SAND 19/5910'. RIH W/ PROD TBG TO 6730'. INIT AND WAIT ON POWER CO	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD Spud Date: Rig Release Date Rig Release Date	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND 20 5910'. RIH W/ PROD TBG TO 6730'. DNIT AND WAIT ON POWER CO e: t of my knowledge and belief.	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD Spud Date: Rig Release Date SIGNATURE **TITLE Engineer** **TITLE Engineer**	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND 7 5910'. RIH W/ PROD TBG TO 6730'. DNIT AND WAIT ON POWER CO 1: 1: 1: 1: 1: 1: 1: 1: 1:	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD Spud Date: Rig Release Date SIGNATURE ### TITLE Engineer Type or print name Sophie Mackay E-mail address:	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND 20 5910'. RIH W/ PROD TBG TO 6730'. DNIT AND WAIT ON POWER CO e: t of my knowledge and belief.	
08/21/08 FRAC TUBB W/ 36K GALS PAD AND 82K LBS 20/40 S 08/22/08 POOH RBP @ 6290'. PERF BLINEBRY @ 5597-5601, 56 08/25/08 SET RBP @ 5910'. ACID BLINEBRY W/ 3000 GALS 159 08/26/08 FRAC BLINEBRY W/ 36K GALS PAD AND 82K LBS 20 08/27/08 TAG FILL @ 5600'. CLEAN OUT FILL. POOH W/ RBP @ 08/28 - 08/29/08 PU PUMP AND RIH W/ RODS. SET PUMPING U 09/04/08 PUT ON PRODUCTION BLINEBRY/TUBB/DRINKARD Spud Date: Rig Release Date SIGNATURE TITLE Enginee Type or print name Sophie Mackay E-mail address: For State Use Only	AND 22-26, 5720-26, 5778-84, 5862-68' 2 JSPF 6 HCl 6/40 SAND 7 5910'. RIH W/ PROD TBG TO 6730'. DNIT AND WAIT ON POWER CO 1: 1: 1: 1: 1: 1: 1: 1: 1:	

APPROVED BY:
Conditions of Approval (Tany):