

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88201
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-04335
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Eunice Monument South Unit
8. Well Number 105
9. OGRID Number 005380
10. Pool name or Wildcat Eunice Monument: Grayburg-San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator XTO Energy, Inc.
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701
4. Well Location Unit Letter <u>D</u> : <u>660'</u> feet from the <u>North</u> line and <u>990'</u> feet from the <u>West</u> line Section <u>25</u> Township <u>20S</u> Range <u>36E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Clean Out, Stimulate & Squeeze Well ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/23/08 MIRU PU. POOH w/57 D-90 7/8" rods & found body brk due to pitting. PU & RIH w/FT. POOH w/rods and FT.

8/26/08 BWTT. ND WH. Re1 TAC. NU BOP. RU scanalog trk. Scan out of hole w/24 jts of 2-7/8" J-55 tbq. RD. Latch onto rods. Screw onto SV. Unseat SV & POOH LD rods. RU scan equip. Scan out of hole w/128 jts total of 2-7/8" J-55 prod tbq. RD Scan equip.

Procedure Cont'd on next page.

Spud Date:

08/23/08

Rig Release Date:

08/30/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kristy Ward TITLE Regulatory Analyst DATE 11/06/08

Type or print name Kristy Ward E-mail address: kristy_ward@xtoenergy.com PHONE 432-620-6740

For State Use Only

APPROVED BY Tyrell Hill TITLE DISTRICT SUPERVISOR/GENERAL MANAGER DATE NOV 13 2008

Conditions of Approval (if any):

Eunice Monument South Unit #105
Clean Out, Stimulate & Squeeze Well Cont'd.
Page 1

8/27/08 MI rack 4,000' of 2-7/8" N-80 tbg. PU & RIH w/sonic hammer tool on 2-7/8" N-80 tbg. Tag @ 4,060' (PBTB). PUH to 3,740'. RU acidizing equip. Wash GB OH fr 3,740' - 3,910' w/280 BBW @ 6 BPM, 2,500 psig. Acidize GB OH fr 3,910' - 3,740' w/2,500 gals of 20% 90/10 acid. Flushed w/40 BFW. ISIP "1,275" psig, 5" Vac. RD. RU swab. RD.

8/29/08 BWTT. POOH LD 2-7/8 N-80 tbg. PU & RIH w/ 127 jts of 2-7/8" J-55 prod tbg. ND BOP. Set TAC w/ 18 pts tens. NU WH.

8/30/08 BWTT. PU & RIH w/pmp & rods as followed. 1-1/4" x 8' GA (New), 2.5 x 2" - RXBC - 24' x 3' pmp. 7/8" x 4' stabilizer sub (New), 8 - 1-1/2" K-Bars (New), 72 - 3/4" D-90 rods (New), 78 - 7/8" D-90 rods (New), 3 - 7/8" D-90 subs (New - 8',4',2') & 1-1/2 x 26' SM PR. RU pmp trk. L&T tbg w/10 bbls of 2% KCL wtr. Pmp up to 500 psig in 4 strks. RD. **RDMO PU. RWTP.**

10/13/08 In 24 hrs, well made 6 BO, 353 BW & 7 MCF.