	New Mcsico (1)	د. ۱۹۹۵ میرونونونونونونونونونونونونونونونونونونون	in Destrict I	
AND DEPARTMENT OF THE INTERIOR OF MALESCAR		(185 5 5 5 5 5 1 m -	FORMAPPI OM B No 1	ROVED 004-0137 arch 31, 2007
BUREAU OF LAND MANAGEMENT			5. Lease Serial No.	arch 51, 2007
NOV 1 A SHADRY NOTICES AND REPORTS ON WELLS			LC-068474	
NOV 1 A 2008 this form for proposals to drill or to re-enter an			6. If Indian, Allottee or	Tribe Name
Abandoned well. Use Form 3160 - 3 (APD) for such proposals.				
	ρ			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7 If Unit or CA/Agree	nent, Name and/or No.
1. Type of Well Gas Well X Other Thiestor			8. Well Name and No	
2. Name of Operator			Drickey Queen Sand Unit #27	
CELERO ENERGY II, LP			9. API Well No.	1
3a. Address 3b. PhoneNo (include area code) 400 W. Illinois, Ste. 1601 Midland TX 79701 (432)686-1883			30-005-01026 10. Field and Pool, or E	valoretori Arro
4. Location of Well (Footage, Sec, T, R., M., or Survey Description)			Caprock Queen	xpioratory Area
660 North 1980 East /			11. County or Parish, S	late
UL: B, Sec: 10, T: 14S, R: 31E			Chaves	/
· · · · ·	-		NM	V
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	SION TYPE OF ACTION			
	Acidize Deepen	Production (Sta	art/Resume) Water S	Shut-Off
Noticeof Intent	AlterCasing Fracture	Treat Reclamation	X Well In	tegrity
Subsequent Report	Casing Repair New Con	struction Recomplete	X OtherR	eactivate
	Change Plans Plug and A	Abandon 🔲 Temporarily Ab	oandon <u>injec</u>	or
Final Abandonment Notice	Convert to Injection	K Water Disposal		
If the proposal is to deepen dire Attach the Bond under which t following completion of the inv	ted Operation (clearly state all pertinent details, ir ectionally or recomplete horizontally, give subsur the work will be performed or provide the Bond I volved operations. If the operation results in a mu- nal Abandonment Notices shall be filed only after y for final inspection.)	face locations and measured and t No. on file with BLM/BIA. Require a second se	true vertical depths of all pert ired subsequent reports shall in a new interval, a Form 31	nent markers and zones. be filed within 30 days 60-4 shall be filed once
pump 500 gals toluene, pump 1250 gals acid tolu TLTR=100 bbls. Had 22 down to 2500' from surfa w/safety collar 2 3/8" & F & pkr. TIH w/nickel plate pkr. Pressured it up. He	n tbg & pkr. CO to 3072'. Run C 2000 gals of 7.5% NEFE acid & 5 uene mix & 20 bbls of wtr. TP 16 20# increase from salt. Well was ace. Made 24 swab runs & recov PU 2 7/8" workstring. Tagged pkr ed 5 ½" x 2 3/8" w/on off tool & ar eld. ND BOP. Got off on off tool. & ran chart for 30 mins. Set pkr built.	500# rock salt. Pumped 50#, Avg=TP 1501#, 4. on vacuum. Tagged fli ered 100 bbls fluid 2% @ 3020'. Screwed on rowset. PU 96 jts IPC, HU WH. Circulated p	d 1250 gals, drop 50 5 bpm, ISIP=677, 3 uid @ 1800' from su oil cut & little gas. 6 to pkr. Unset, pulle 2 3/8" J-55, 4.7#, 8 kr fluid 70 bbls. Go	00# rock salt & mins=on vacuum, irface. Swabbed hrs swabbing. TIH d, & LD workstring rd EUE tbg. Set t back on pkr
Original chart sent to OC Order No. R-1128 (2/12/	(58)			
 I hereby certify that the foreg Name (Printed/Typed) 	going is true and correct	1		
Lisa Hunt	1	Title Regulatory Ana	lyst	
Signature Lisa) Hunt	Date 11/07/2008		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
ACCEPTED FC	RECORD			
Approved AS-DAVII	Breitee	T Accepted Fo	or Record Only!	Approval

d

-- --

Conditions the application of th Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person States any false, fict Days in fraudical signments or representations as to any matter wi (Instructions on page 2) UMENGINEER

5

Subject To Returning Well To Continuous Injection And Keeping Well On Continuous Injection Or Plugging Well With An Approved Plugging Program!



