	DEPARTMENT OF	STATES THE INTERIOR		FORM APPROVED OMB No 1004-0137
	BUREAU OF LAND		OCD-HO	BBS Expires July 31, 2010
SUND	RY NOTICES AND		•	NMNM70988X
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals			6 If Indian, Allottee or Tribe Name	
			LC 059576	
SUBMIT I	N TRIPLICATE - Oth	ner instructions on	page 20 V	7 If Unit or CA/Agreement, Name and/or No
1 Type of Well			TAN SO	Maljamar Grayburg
Oil Well Gas Well	Other		NOS S	8 Well Name and No
2 Name of Operator	1	./		Maljamar Grayburg Unit 13 🖌
Forest Oil Corporation		·		9 API Well No
3a Address	1	Phone No (include area co	de)	30-025-00444
707 17 th St. Ste. 3600, Den 4 Location of Well (Footage, Sec., T.		03-812-1554		10 Field and Pool, or Exploratory Area
Sec. 3, T-17-S, R-32-E	R, W, Or Survey Description,	/	/	Maljamar Grayburg
660 FSL & 660 FEL				Lea Co. NM
	PPROPRIATE BOX(F	S) TO INDICATE NA	TURE OF NOTICE R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		S, IO INDICATE NA	TYPE OF ACTION	
THE OF SOBWISSION			[]	
Notice of Intent		Deepen	Production (Start/Resi	
V	Alter Casing	Fracture Treat	Reclamantion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonmeht Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
-	Convert to Injection	Plug Back	Water Disposal	
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB	al Abandonment Notices sh r final inspection) . Unset packer. SDF] IPC tbg.	ation results in a multiple all be filed only after all N.	completion or recompletion requirements, including recl	in a new interval, a Form 3160-4 shall be filed one
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cei 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull o 010'. POH to 1100'. g plug @ 1142'. SD	ation results in a multiple all be filed only after all N. O. Circulate hole wa et packer @ 2100'. Hout of cement. WOC Perf. csg @ 1350'. S for repairs.	completion or recompletion requirements, including recl / mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'.	in a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in.
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cei 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'	al Abandonment Notices sh r final inspection) . Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD (Put swedge on csg. ()	ation results in a multiple all be filed only after all N. O. Circulate hole w/ et packer @ 2100'. H out of cement. WOC Perf. csg @ 1350'. S for repairs.	completion or recompletion requirements, including recl / mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'.	in a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in.
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/06/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/08/08 Perf csg @ 343'	al Abandonment Notices sh r final inspection) . Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD (Put swedge on csg. ()	ation results in a multiple all be filed only after all N. O. Circulate hole w/ et packer @ 2100'. H out of cement. WOC Perf. csg @ 1350'. S for repairs.	completion or recompletion requirements, including recl / mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'.	in a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in.
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cei 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg @ 343'	al Abandonment Notices sh r final inspection) . Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD (Put swedge on csg. ()	ation results in a multiple all be filed only after all N. O. Circulate hole wa et packer @ 2100'. H out of cement. WOC Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location move off	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p 4 hrs. SDFN. Set packer @ 1100'. down casing and up A	in a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in.
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cei 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg @ 343'	al Abandonment Notices sh r final inspection) . Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD (Put swedge on csg. ()	ation results in a multiple all be filed only after all N. O. Circulate hole w et packer @ 2100'. Hout of cement. WOC Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location moxe off NOV 2	completion or recompletion requirements, including recl / mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'.	in a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. p backside to surface: cut off well heat CCEPTED FOR RECORD NOV 4 2008
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/08/08 Unset packer. Ta 10/08/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean	ation results in a multiple all be filed only after all N. O. Circulate hole was to packer @ 2100'. Hout of cement. WOC Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location move off NOV 2	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up f 2 2008	in a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. packside to surface: cut off well hear CCEPTED FOR RECORD
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean	ation results in a multiple all be filed only after all N. O. Circulate hole w. At packer @ 2100'. Hout of cement. WOO Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location moxe off NOV 2 Interview (Title	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up down casing and up 5 2008	In a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. Packside to surface: cut off well heat CCEPTED FOR RECORD NOV 4 2008 NOV 4 2008 DUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean strue and correct)	ation results in a multiple all be filed only after all N. O. Circulate hole w. et packer @ 2100'. H but of cement. WOC Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location moxe off NOV 2 NOV 2	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up down casing and up 52008	In a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. p backside to surface: cut off well heat CCEPTED FOR RECORD NOV 4 2008 NOV 4 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean strue and correct)	ation results in a multiple all be filed only after all N. O. Circulate hole w. et packer @ 2100'. H but of cement. WOC Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location moxe off NOV 2 NOV 2	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up down casing and up 5 2008	In a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. p backside to surface. cut off well heat CCEPTED FOR RECORD NOV 4 2008 NOV 4 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean strue and correct)	ation results in a multiple all be filed only after all N. O. Circulate hole w. et packer @ 2100'. H but of cement. WOC Perf. csg @ 1350'. S for repairs. Sqz'd 80 sx. cement n location moxe off NOV 2 NOV 2	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up down casing and up 52008	si. SDFN. Sqz'd 45 sx cement. Shut well in. Descent and the surface of the surfac
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean rker. Rig down clean THIS SPACE hed Approval of this notice do	ation results in a multiple all be filed only after all N. O. Circulate hole w. At packer @ 2100'. Hout of cement. WOO Perf. csg @ 1350'. St for repairs. Sqz'd 80 sx. cement in location move off NOV 2 NOV 2 FOR FEDERAL C	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up down casing and up $f = c \ v = im_a w$ $f = c \ v = im_a w$ $f = c \ v = im_a w$ $f = c \ v = im_a w$ DR STATE OFFICE	In a new interval, a Form 3160-4 shall be filed one amantion, have been completed, and the operator ha Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. p backside to surface. cut off well heat CCEPTED FOR RECORD NOV 4 2008 NOV 4 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
testing has been completed Fin determined that the site is ready for 09/30/08 MIRU. NU BOP. 10/01/08 POH w/ 110 jts. I 10/02/08 RIH w/ 5 1/2 CIB SDFN. 10/03/08 Perf'd 5 1/2 csg. (10/06/08 Pumped 35 sx cer 10/07/08 Tagged plug @ 2 SDFN. 10/08/08 Unset packer. Ta 10/08/08 Unset packer. Ta 10/09/08 Perf csg. @ 343'. and weld on Dry Hole Ma	al Abandonment Notices sh r final inspection) Unset packer. SDF IPC tbg. BP on tbg. Set @ 375 @ 2350'. RIH and se ment @ 2410'. Pull of 010'. POH to 1100'. g plug @ 1142'. SD Put swedge on csg. S rker. Rig down clean strue and correct) THIS SPACE hed Approval of this notice do le to those rights in the subject	ation results in a multiple all be filed only after all N. O. Circulate hole w. At packer @ 2100'. Hout of cement. WOO Perf. csg @ 1350'. St for repairs. Sqz'd 80 sx. cement in location move off NOV 2 NOV 2 FOR FEDERAL O Title Date FOR FEDERAL O	completion or recompletion requirements, including recl mud laiden fluid. S Pressured up 1500 p C 4 hrs. SDFN. Set packer @ 1100'. down casing and up 5 2008 5 2008 $f = c = m_a w$ $f = c = m_a w$	In a new interval, a Form 3160-4 shall be filed once amantion, have been completed, and the operator has Spot 25 sx cement on top of CIBP. si. SDFN. Sqz'd 45 sx cement. Shut well in. p backside to surface: cut off well head CCEPTED FOR RECORD NOV 4 2008 NOV 4 2008 DURFAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

x

(Instructions on page 2)

1