Office District I Energy, Minerals and Natural Resources	30.025. 03877 June 19, 2008
1605 N. F 1 D. H. H NN 499240	WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II 1301 W Grand Ave, Artesia 018 2008 OIL CONSERVATION DIVISION	30-025 -03887 /
District III 1220 South St. Francis Dr	5. Indicate Type of Lease
1000 Rio Brazos Rd Azien NM 87410 Santa Fe NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr. Santa Pennin 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	WEST LOVINGTON UNIT
1. Type of Well: Oil Well Gas Well Other	8. Well Number 34
2. Name of Operator / CHEVRON MIDCONTINENT, L.P.	9. OGRID Number 241333 /
3. Address of Operator15 SMITH ROAD, MIDLAND, TEXAS 79705	10. Pool name or Wildcat LOVINGTON UPPER SAN ANDRES W.
4. Well Location	
Unit Letter M 660 feet from the SOUTH line and 660 feet from the WEST	line
Section 4 Township 17-S Range 36-E NMPM	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
	ILLING OPNS. P AND A
PULL OR ALTER CASING	II 30B
DOWN TOLL COMMINGEL	
OTHER: INTENT TO TEMPORARILY ABANDON OTHER:	1
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	id give pertinent dates, including estimated date trach wellbore diagram of proposed completion
or recompletion.	
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQ	SUBJECT WELL. THIS WELL HAS
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE	SUBJECT WELL. THIS WELL HAS
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT FUTURE CONSIDERATION OF CONVERTING TO INJECTION.	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT TO INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PL	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT WITH FUTURE CONSIDERATION OF CONVERTING TO INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PISCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" VARIANTE CONTROL OF THE PROPERTY OF THE PROPE	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER WINJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLANGE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD W/ON/OFF TOOL & WORLD W/PKR FLUID. 10) PERFORM MIT FOR PRIMO	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLANGE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD W/ON/OFF TOOL & WORLD W/PKR FLUID. 10) PERFORM MIT FOR PRIMO	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLANGE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD W/ON/OFF TOOL & WORLD W/PKR FLUID. 10) PERFORM MIT FOR PRIMO	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLANGE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD W/ON/OFF TOOL & WORLD W/PKR FLUID. 10) PERFORM MIT FOR PRIMO	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
Or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH WW/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLOW OF SCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" VINSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior of the proventies of the provent	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLANGE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD BRINE W/2" V/ON/OFF TOOL & WORLD W/ON/OFF TOOL & WORLD W/PKR FLUID. 10) PERFORM MIT FOR PRIMO	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
Or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH WW/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLOW OF SCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" VINSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior of the proventies of the provent	SUBJECT WELL. THIS WELL HAS PT & T/A WITH AN INJECTION PACKER V/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11)
Or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT & OUR INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH WW/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE & PLOW OF SCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" VINSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior of the proventies of the provent	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER WINJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart
Or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH WW/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE. & PISCONNING & LD TBG. 8) NDBOP. NUWH W/BI 3000# FLANGE W/2" VAIN INSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior office 24 hours prior Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled.	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER WINJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart
Or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH WW/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 6) CIRC W/10# BRINE. & PISCONNING & LD TBG. 8) NDBOP. NUWH W/BI 3000# FLANGE W/2" VAIN INSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior office 24 hours prior Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled.	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER W/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IN EXAMPLE TO INJECTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) THE W/ON/OFF TOOL @ 4640. 50' ABOVE PERFS 69 CIRC W/10# BRINE & PI SCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" V. INSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. LOAD HOLE W/IN EACH Flux d Condition of Approve office 24 hours prior of Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE WILL WALL TO TITLE REGULATORY SPECIFICATION.	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER W/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart ge and belief. ALIST DATE 12-01-2008
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IN EXAMPLE OF TOOL @ 4640. 50° ABOVE PERFS 6) CIRC W/10# BRINE & PISCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" VAINTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior office 24 hours p	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER W/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart ge and belief. ALIST DATE 12-01-2008
Or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IN INTENTION. 1) MIRU. KILL WELL. 2) NDWH. NUBOP. 3) TOH W/SUBPUMP. 4) TIH V W/ON/OFF TOOL @ 4640. 50° ABOVE PERFS 6) CIRC W/10# BRINE & PI SCANNING & LD TBG. 8) NDBOP. NUWH W/BI 3000# FLANGE W/2" V. INSTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior office 24 hours prior Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE REGULATORY SPECIAL TYPE OF PRIOR TO THE REGULATORY SPECIAL TYPE OF PRIOR TYPE OF PRIOR TYPE OF State Use Only	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER W/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart ge and belief. ALIST DATE 12-01-2008 PHONE: 432-687-7375
or recompletion. CHEVRON MIDCONTINENT, L.P. INTENDS TO TEMPORARILY ABANDON THE SUBMERSIBLE EQUIPMENT & OUR INTENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IS TO REMOVE SUBMERSIBLE EQUIPMENT IN EXAMPLE OF TOOL @ 4640. 50° ABOVE PERFS 6) CIRC W/10# BRINE & PISCANNING & LD TBG. 8) NDBOP. NUWH W/B1 3000# FLANGE W/2" VAINTALLED. 9) TOP OUT WELL W/PKR FLUID. 10) PERFORM MIT FOR RDMO. Condition of Approve office 24 hours prior office 24 hours p	SUBJECT WELL. THIS WELL HAS OPT & T/A WITH AN INJECTION PACKER W/INJ PACKER. 5) SET INJ PACKER RETEST CSG TO 500 PSI. 7) TOH ALVE ON TOP W/PRESSURE GAUGE R NMOCD: 500 PSI FOR 30 MINUTES. 11) al: Notify OCD Hobbs r to running MIT Test & Chart ge and belief. ALIST DATE 12-01-2008 PHONE: 432-687-7375