

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE *
(Other Instructions on
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

OCD Hobbs

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC-059576	
2. NAME OF OPERATOR The Wiser Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		7. UNIT AGREEMENT NAME Maljamar Grayburg Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 15' FNL & 2478' FEL Unit B		8. WELL NAME AND NO. 95	
		9. API WELL NO. 30-025-32039	
		10. FIELD AND POOL, OR WILDCAT Maljamar Grayburg San Andres	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10-T17S-R32E	
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4196' GR	12. COUNTY OR PARISH Lea County	13. STATE NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>

(Other) Temporary Abandon

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT * <input type="checkbox"/>


(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Wiser request approval to Temporary Abandon the well by the procedure listed below:

Perfs: 3371'-3392'

- TOH w/pump and rods. TIH w/CIBP and set @ 3300'.
- Spot or dump 25' cement on plug. ← 35' 
- Pressure test plug and casing to 500#.
- If holds circulate packer fluid.
- POH w/tbg.
- Pressure test casing to 500# with a pressure recorder.
- Shut well in.

*Note: Call OCD Hobbs Office before beginning work.

Call BLM @ 505.393.3612

** TA'D the well will enable Wiser to evaluate the Queen gas.

18. I hereby certify that the foregoing is true and correct.

SIGNED  TITLE Production Superintendent DATE October 24, 2003

(This space for Federal or State office use)

APPROVED BY (ORIG. SCD) JOE G. LARA TITLE Production Superintendent

CONDITIONS OF APPROVAL, IF ANY:

DATE 11/21/03

*See Instruction On Reverse Side

