FORMAPPROVED OM B No 1004-013 Expires March 31, 2007 PARTMENT OF THE INTERIOR OCD-HOBES Serial No. BUREAU OF LAND MANAGEMENT UEC OSUMPRY NOTICES AND REPORTS ON WELLS LC029405A 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an HOBBSOEDell. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 892003410 1. Type of Well Oil Well X Other Gas Well 8. Well Name and No. MCA Unit #54 2. Name of Operator 9. API Well No ConocoPhillips Company 30-025-08039 3b. PhoneNo. (include area code) 3a. Address (432)688-6884 10. Field and Pool, or Exploratory Area 3300 N. "A" Street, Bldg. 6 Midland TX 79705 Maljamar GB/SA 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1980' FNL & 1980' FWL Lea County UL: F, Sec: 19, T: 17S, R: 32E **New Mexico** 12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION _ Acidize Deepen Production (Start/Resume) ☐ Notice of Intent Alter Casing Reclamation Well Integrity FractureTreat] OtherReclaim Casing Repair New Construction Recomplete Subsequent Report Location Change Plans Plug and Abandon inal Abandonment Notice Convert to Injection ☐ Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1. Remove flow and injection lines. 2. Remove caliche and contaminated soil from location and transport to CRI disposal. 3. Replace with clean caliche up to 2' from surface to form barrier. 4. Cap last 2' with clean topsoil. 5. Level and shape for seeding. 6. Reseed all disturbed areas with BLM #2 seed mixture with BLM approved seeder. Reclaimed location with BLM recommendations and met with BLM, Trish Badbear, prior to start-up procedures. Reclaim complete on 10-17-08 by McNabb Services. BLM was notified upon completion and seeding for them to witness and approve. I hereby certify that the foregoing is true and correct