RELEASE \ P/	I'L DK TO KELEASE
PECELLASE PINALENSE PINALENSE PINALENSE	1'd. OK TO KELEASE.
OCT 27 2008 NEED TO REMOVE Submit 2 Copies To Appropriate District ZTANKS, Yellow Marker elicultury. State of New Mexico	
Submit 2 Copies To Appropriate District State of New Mexico Office Minorals and Netural Possurous	Form C-103 October 25, 2007
Office District 1:4 Property Minerals and Natural Resources 1625 N. Trench District II District II OIL CONSERVATION DIVISION	WELL API NO. 30-005-21039
District III OIL CONSERVATION DIVISION District III 1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Thelma
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 1-Y
2. Name of Operator Hanson Operating Company, Inc.	9. OGRID Number / 009974
3. Address of Operator	10. Pool name or Wildcat Cato San Andres
P. O. Box 1515, Roswell, NM 88202-1515 4. Well Location	Cato san Andres
Unit Letter K: 1980 feet from the South line and 2010 feet from the West line Section 7 Township 9 South Range 30 East NMPM Chaves County NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 4041.2 GL	:)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE	RK
TEMPORARILY ABANDON	
OTHER:	ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, Q	UARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(t) 	o) NMAC. All fluids have been removed from
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Carol f. Smith TITLE Production Analys	DATE 10/24/2008
TYPE OR PRINT NAME <u>Carol J. Smith</u> E-MAIL: <u>hanson@dfn.c</u>	om PHONE: <u>575-622-7330</u>
For State Use Only	INTO I I I I I I I I I I I I I I I I I I I
APPROVED BY: TITLE COnditions of Approval (if any):	DATE 12/2/2008
Conditions of Approval (if any): COMPLIANCE OFFICER	
	-