Submit 3 Copies To Appropriate District	State of New Mexico				Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Resources			WIDE A DENO	Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30 - 625	-79811
1301 W. Grand Ave., Artesia, NM 88210				5. Indicate Type	of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			STATE		
<u>District IV</u> Santa Fe, NIVI 8/303			6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name o	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				New Mexico BM	
PROPOSALS.)				8. Well Number	
1. Type of Well:				8. Well Nulliber	
Oil Well Gas Well Other					,
2. Name of Operator PENROC OIL CORPORATION					17213
3. Address of Operator P-O-Box 2769, Hobbs, NM 88241				10. Pool name or	r Wildcat
4. Well Location					
Unit Letter 0: 33 feet from the S. line and 1652 feet from the line					
Section 16 Township 17 S Range 36 E NMPM County Lea					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
	PLUG AND ABANDON	XI	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON			LLING OPNS.□	PLUG AND  ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE [ COMPLETION		CASING TEST AN CEMENT JOB	ID 🗆	, is a second se
OTHER:	ļ		OTHER:		
13. Describe proposed or comple	eted operations. (Clearly st	tate all p	ertinent details, and	l give pertinent dat	es, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
P1/ 1/21	D // */ + =	tuba	a in the he	de RII	Wireling Set
RU WSU. Pull if any tubing in the hole. RU Wireline - Set					
052627283 CIBP @ 5100'. TIH, W/ Hbg. Spot 35' cement on					
top of CIBP. Circulate hole of 9.3 gelled brine.					
Spot 25 5x coment plug 4250-4150'. POH to					
CTBP @ 5100'. TIH, W/ the . Spot 35' cement on top of CTBP. Circulate hole of 9.3 gelled brine.  Spot 25 5x cement plug 4250'-4150'. POH to  450'. 3pot 25x. plug. Spot 10 sx @ surface.  Dustall dryhole marker. Clean up booth per NMOCB repulations.					
E Hobbs A	750 . Spor C	. /	D marke	V Class	as frater
oco os	Distall of	who	Ce Marac	s. Gean	<i>ag-</i> 700,277
9191	per NMOC	· L	erulations.		
10111213191	/				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE Up L TITLE Thick DATE 4/25/03					
Type or print name M-4. Merchant E-mail address: my merchant hat mail. con Telephone No. 505/492-123					
(This space for State use)					
APPPROVED BY Mo College Title Date					
APPPROVED BY					