

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32684
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

oil well ☒ gas well ☐ other ☐

2. Name of Operator

Nearburg Producing Company

3. Address of Operator

3300 N. A St., Bldg. 2, Suite 120, Midland, TX 79705

4. Well Location

Unit Lease G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 20 Township 17S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3768' GR

7. Lease Name or Unit Agreement Name

Shipp 20

8. Well No.

1

9. Pool name or Wildcat

Midway; Strawn, South

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-11-03 Spot 25 sx cmt. from 10,800' WOC & tag @ 10,610'.
- 11-11-03 Circ. w/ 235 bbls. 9.5# mud gel.
- 11-11-03 Spot 25 sx cmt. from 9600' to 9374'.
- 11-11-03 Spot 25 sx cmt. from 7000' to 6774'.
- 11-12-03 Spot 70 sx cmt. @ 5275' on 5-1/2" csg. stub & 8-5/8" shoe WOC & tag @ 5060'.
- 11-13-03 Spot 35 sx cmt. from 3000' to 2886'.
- 11-13-03 Sqz. 70 sx cmt. from 2050' WOC & tag @ 1930'.
- 11-14-03 Spot 55 sx cmt. from 1060' WOC & tag @ 935' 8-5/8" casing stub.
- 11-14-03 Spot 75 sx cmt. from 450' WOC & tag @ 338'.
- 11-14-03 Spot 35 sx cmt. from 60' to surface.
- 11-14-03 RDMO. Cut off wellhead, install dry hole marker, & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Roger Massey

TITLE

Agent

DATE

11-19-03

TYPE OR PRINT NAME

Roger Massey

TELEPHONE NO.

432-530-0907

OC DISTRICT SUPERVISOR/GENERAL MANAGER

(This space for State Use)

APPROVED BY

Chris Williams

TITLE

DATE

DEC 01 2003

CHARACTER OF APPROVAL, IF ANY