Form 3160-5 (August 1999)

N.M. Oil Cons. Division

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT HODDS, NM 88240

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5.	Lease Serial No.	
	NM 94864	
6	If Indian Allottee or Tri	he Name

SUBMIT IN TR	IPLICATE - Other Instru	ictions on reverse	side 🚈 🚎	7. If Unit o	r CA/Ag	greement, Name and/or No.
. Type of Well		<u>্রতি এটা হেটা - এটাটান্থক প্রশিক্ষীয়ন্ত্</u>				
Oil Well Gas Well	Other			8. Well Na	me and	No.
. Name of Operator			P. W	EL ZORR	O FR	EMONT FED. #2
LAYTON ENTERPRIS				9. API Wel	ll No.	
a. Address 3103 79th S		3b. Phone No. (include	area code)	30-0	25-3	4703
Lubbock, Te: Location of Well (Footage, Sec.	tas 79423	806/745-4638				or Exploratory Area
1880' FNL) · · ·				evonian
Sec 1, T9S,				11. County of Lea C		y, New Mexico
TYPE OF SUBMISSION		T	PE OF ACTION			
Notice of Intent	☐ Acidize	Deepen Deepen	Production	(Start/Resume)	<u> </u>	Water Shut-Off
trode of intent	Alter Casing	☐ Fracture Treat	Reclamation	1	Q ,	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete			Other
☐ Final Abandonment Notice	Change Plans	Plug and Abandon		y Abandon		PLUG BACK
C rinal Abandonment Notice	Convert to Injection	Plug Back	Water Disp			
determined that the site is read Intend to set C	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @	be filed only after all requ	irements, including	reclamation, have		
Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold. is indicated, the	be filed only after all requests of 6" 3000 tested zone(s)	ement on to ossible pro # Double Ra will be so	p to covered to p to covered to c	r Dev s ind or	vonian dicated he bridge plug
Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold.	be filed only after all requests of 6" 3000 tested zone(s)	ement on to ossible pro # Double Ra will be so	p to covered to the property of the covered to the	r Dev s ind or	vonian dicated
Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif If no production drilled out, and	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold. is indicated, the the well returned	be filed only after all required to the filed only after all required to the filed only after all required to the filed to	ement on to ossible pro # Double Ra will be so from the Da	p to covered to the property of the covered to the	r Dev s inc or or f, th	vonian dicated he bridge plug
Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif If no production drilled out, and 14. I hereby certify that the foreg Name (Printed/Typed) DONALD R. LAY	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold. is indicated, the the well returned	be filed only after all required to the filed on	ement on to ossible pro # Double Ra will be so	p to covered to the property of the covered to the	r Dev s inc or or f, th	vonian dicated he bridge plug
Intend to set C Perfs 12,384 - 1 Intend that the site is read Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif If no production drilled out, and	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold. is indicated, the the well returned	be filed only after all required 12,330 w/5 sx of elow 9500 for present of 6" 3000 tested zone(s) to production Title	ement on to ossible pro # Double Ra will be so from the De	p to covered and prevent queezed of evonian Zor	r Dev s inc or or f, th	vonian dicated he bridge plug
Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif If no production drilled out, and 14. [hereby certify that the foreg Name (Printed/Typed) DONALD R. LAY	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold. is indicated, the the well returned	be filed only after all required to the filed on	ement on to ossible pro # Double Ra will be so from the De	p to covered and prevent queezed of evonian Zor	r Dev s inc or or f, th	vonian dicated he bridge plug
Intend to set C Perfs 12,384 - 1 Intend then to t by log studies. Blowout prevento with choke manif If no production drilled out, and 14. I hereby certify that the foreg Name (Printed Typed) DONALD R. LAY Signature	Final Abandonment Notices shall y for final inspection.) I. Bridge Plug @ 2,416. est Penn Zone(s) be r program will consold. is indicated, the the well returned	be filed only after all required 12,330 w/5 sx of elow 9500 for production tested zone(s) to production Title Date	ement on to ossible pro # Double Ra will be so from the De	p to covered by to covered and prevent queezed of evonian Zor	r Dev s inc or or f, th	vonian dicated he bridge plug