

# NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

#### BILL RICHARDSON

Governor Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director Oil Conservation Division

\*Response Required - Deadline Enclosed\*

19-Dec-08

## PLATINUM EXPLORATION INC

550 WEST TEXAS AVENUE SUITE 500 MIDLAND TX 79701-

### **LETTER OF VIOLATION - Inactive Well(s)**

#### Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

# IDLE WELL INSPECTION DETAIL SECTION

**ROSE EAVES 002** 

P-35-16S-38E

30-025-07291-00-00

Inspection No. iJRH0835452650

**Inspection Date:** 

12/19/2008 2:37:07 PM

Corrective Action Due by: 3/24/2009

**Type Inspection** 

Inspector

Violation?

\*Significant Non-Compliance?

Complaint Response

John Harrison

Yes

Nο

Comments on Inspection:

NO WELL SIGN (RULE 103), IDLE WELL (RULE 201), PIT OPEN AND FENCED, LINER IS TORN, NO PUMPING UNIT, NO FLOW LINES, LOCATION NEEDS ATTENTION. THIS IS 1ST

LETTER OF NON-COMPLIANCE, JRH

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Hobbs OCD District Office

<sup>\*</sup> Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240

 $2\gamma \gamma^{i}$ 



017H1555a017 BBV SQL AVERAGE S

PLATINUM EXPLORATION INC. 550 W TEXAS AVE SUITE 500 MIDLAND, TX 79701