State of New Mexico RECEIVE Phergy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CO	ONSERVA	ATION DIVISION	N			1
DISTRICT I 1625 N French Dr., Hobbs, NM 883	DEC 27 7915 1220 South St. Francis Dr. Santa Fe, NM 87505			WELL API NO 30-025-0'	WELL API NO 30-025-07464		
DISTRICT II HOBBSOCD				1	5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88	210			i	ATE	FEE X	4
DISTRICT III	10			6 State Oil & G	as Lease No		
1000 Rio Brazos Rd, Aztec, NM 87410				7 Lease Name of	or Unit Agreemer	nt Name	-
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					North Hobbs (G/SA) Unit		
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)					Section 30		
1. Type of Well.					121	,	7
Oıl Well X Gas Well Other							
2. Name of Operator Occidental Permian Ltd.					9. OGRID No. 157984		
3 Address of Operator					r Wıldcat	Hobbs (G/SA) V	7
1017 W. Stanolind Rd., Ho	obbs, NM 88240						4
4. Well Location							
Unit Letter <u>E</u> 2	Feet From The	North	330	Feet From The	West	Line	
Section 30	Township	18-S	Range	38-E NMPN	Л	Lea County	
	11. Elevation (Show)		B, RT GR, etc)				
	3650' GL						
Pit or Below-grade Tank Applica	ation or Closure						
Pit Type Depth of	1 1	stance from no	parast frash water well	Dictance fro	om nearest surf	ace water	
					Jili licarest suri	ace water	
Pit Liner Thickness	mil Below-Grade Tank:	voiume	bbls; Construction	n Materiai			
12.	Check Appropriate Box to	Indicate Nat			TROPT OF		_
NOTICE O	F INTENTION TO:		8	UBSEQUENT RI	EPURT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDO	NC	REMEDIAL WORK		ALTERING (CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS	PLUG & AB	ANDONMENT	
PULL OR ALTER CASING	Multiple Completion		CASING TEST AND CE	MENT JOB			
OTHER			OTHER. OAP/A	Acid treat		X	
13 Describe Proposed or Comple	eted Operations (Clearly state)	all pertinent de	tails and give pertinent	dates including estim	ated date of sta	rting any	=
	E 1103. For Multiple Completic					iting uny	
FF			.	•	•		
1. RU PU AND REV UNIT	S 10 II DDDIE						
 KILL TBG W/ 15 BBLS OF TBG @ 4020' 	10# BRINE				5		
4. KILL CSG W/ 125 BBLS C	OF 10# BRINE, KILL TBG W	// 30 BBLS C	F 10# BRINE				
5. POOH W/ 2 7/8 TBG AND							
6. TBG-3969'							
7. KILL TBG W/ 25 BBLS OF		W/ 80 BBLS (OF FRESH WTR				
8. RIH W/ 4 ¼ BIT, TAG @ 4 9. FILL FROM 4266' TO 429							
y. 112211totti 1200 10 12	2 1110 50215						
			TTACHED***				_
I hereby certify that the information a constructed or	above is true and complete to the b	est of my knowl	edge and belief. I further co	ertify that any pit or belo	w-grade tank has	been/will be	
closed according to NMOCD gui	idelines , a general p	ermit -	or an (attached) altern	native OCD-approved			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		plan	· · · · · · · · · · · · · · · · · · ·			
SIGNATURE //	a K. Kar	men	TITLE Administra	ntive Associate	DATE	12/11/08	
TYPE OR PRINT NAME Rebe	ecca L. Larmon E-ma	ul address.	rebecca_larmon@oxy		EPHONE NO.	575-397-8247	
For State Use Only	2//,-		nctral	ENU ENGINEE	4	DECAG	_ ባለለና
APPROVED BY	2 lans		_ TITLE		DATE	DEC 22	<u>LU</u> Ut
	NV:						

- 10. SET PLUG @ 4117', SET PKR @ 4006'
- 11. TEST SQUEEZED PERFS FROM 4042' TO 4092'
- 12. RELEASE PKR AND PLUG, POOH TO 3000'
- 13. KILL TBG W/ 15 BBLS OF FRESH, KILL CSG W/ 80 BBLS OF FRESH WTR.
- 14. PERFORATE 5" LINER @ 4125'-30, 2JSPF, 180 DEFREE SPIRAL
- 15. PKR SET @ 4187'
- 16. ACIDIZE PERFS FROM 4196' TO 4283'
- 17. RIH W/ 5" PPI TOOL W/ 43' SPACING, SET TOOLS IN BLANK PIPE ABOVE ALL PERFS @ 4000'
- 18. ACIDIZE PERFS @ 4148'-81' AND 4125'-30'
- 19. SET PKR @ 3950'
- 20. BOTTOM OF ESP @ 3827', INTAKE @ 115-2 7/8 JTS
- 21. RD PU AND REV UNIT

RU PU 10/15/08 RD PU 10/20/08