

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

DEC 3.0 2008

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

5 Lease Serial No.

						_
ı	٧N	1-9	97	1	6	5

JAMES A. AMOS

SUNDRY NOTICES AND REPORTS ON WELLSOBBSOC

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. I Type of Well 8. Well Name and No. Oil Well Other Gas Well Ed Powell BGP Federal 1 2. Name of Operator 9. API Well No. Lime Rock Resources A, L.P. 30-025-33793 3a Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area Heritage Plaza, 1111 Bagby; Suite 4600; Houston, TX, 77002 Dublin Devonian, East (713) 292-9514 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Section 7-T26S-R38E 330' FSL & 1,880' FWL (Unit N, SESW) Lea County, New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Water Shut-Off Production (Start/Resume) Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Subsequent Report Change Plans ✓ Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 11/12/2008: MIRU. POOH with rods and pump. 11/13/2008: ND wellhead. NU BOP's. Unset anchor. 11/17/2008: POOH with tubing. RIH & set CIBP @ 9,960' - dump 35' cment on top of plug. 11/18/2008: RIH with tubing. Rig broke down. 11/19/2008: Circulate hole with mud. Pick up to 8,937'. Spot 25 sxs cement plug. POOH. RIH with packer to locate hole in casing. 11/20/2008: SD due to wind. 11/21/2008: Found hole in casing from 6,780' to 6,792'. POOH. 11/24/2008: RIH & perforate 5-1/2" casing @ 8,194'. POOH. RIH with packer and tubing. Pump 55 sxs cement. POOH & WOC. 11/25/2008: RIH & tag cement @ 8,006'. POOH. ND BOP's & NU wellhead. RIH & cut casing @ 7,987'. 11/26/2008: MIRU casing jacks. POOH with 2 joints 5-1/2" casing. 12/01/2008: POOH & lay down 170 joints 5-1/2" casing. 12/02/2008: NU BOP's. RIH & spot 45 sxs @ 7,062'. POOH & WOC. RIH & tag cment @ 5,885'. POOH to 5,427' & spot 55 sxs cement. POOH & WOC. 12/03/2008: RIH & tag cement @ 5,231'. POOH & spot 60 sxs @ 4,257'. POOH & WOC. RIH & tag cment @ 4,145' (30' low). 12/04/2008: RIH & tag cement @ 4,145' & top off with 25 sxs cement. POOH & WOC. RIH & tag cement @ 4,051'. POOH to 2,665' & spot 40 sxs cement. POOH to 1,300' & spot 40 sxs cement. POOH to 520' & spot 40 sxs cement. POOH & WOC. 12/15/2008: RIH & tag cement @ 370'. POOH. ND BOP's. RIH to 60' & circulate 20 sxs cement to surface. Dig out cellar & cut off wellhead. Install P&A marker. Level location. Cut-off anchors. RD. Approved as to plugging of the well bore. Well is P&A'd. Liability under bond is retained until Surface restoration is completed. 14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) C. Tim Miller Title Vice President - Operations Signature Date 12/09/2008 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by 1 6 2008 Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Office

Title 18 U S C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department of agency of the United States any false,

entitle the applicant to conduct operations thereon

that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction



FINAL ABANDONMENT

gara é

Circulated cement from 60' back to surface

🙎 11-3/4", 42#, H-40, ST&C Casing @ 462'

Spotted 40 sx plug from 520' to 370' (tagged top of plug)

Spotted 40 sx plug @ 1,300'

Spotted 40 sx plug @ 2,665'

8-5/8", 32#, J-55 & HC-80, ST&C Casing @ 4,170'

Spotted 85 sx plug from 4,257' to 4,051' (tagged top of plug)

Spotted 50 sx plug from 5,427' to 5,231' (tagged top of plug)

Spotted 50 sx plug from 7,062' to 6,885' (tagged top of plug)

Cut 5-1/2" casing @ 7,987'

Perforated at 8,194' and pumped 55 sx cement

Spotted 25 sx plug @ 8,937'

TOC @ 8,400'

Set Cast Iron Bridge Plug @ 9,960' and spotted 35' cement on top of plug (tagged top of plug) $\,$

Devonian Perfs: 10,010-46' (37 - 0.42" DIA holes)

CIBP @ 10,460' w/ 35' cement on top

<u>Fusselman Perfs</u>: 10,513-528' (96 - 0.45" DIA holes)

CIBP @ 11,010' w/ 35' cement on top Ellenburger Perfs: 11,051-60' (20 - 0.42" DIA holes)

PBTD @ 10,679' 5-1/2"; 17#; J-55, L-80, N-80, & S-95; LT&C Casing

5-1/2"; 17#; J-55, L-80, N-80, & S-95; LT&C Casing @ 11,722'

TD @ 11,722'

Lime Rock Resources Ed Powell BGP Federal 1 Sec 7N-26S-38E Lea County, NM