Submit 3 Copies To Appropriate		,
District Office	State of New Mexico	Form C-103
1625 N. French Dr., Hobbs, NM 88240	nergy, Minerals and Natural Resource	WELL API NO. 30-025-10461
1301 W Grand Ave , Artes A May 5 88210	CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NAAN 05 2	1220 South St. Francis Dr.	STATE FEE
87410		6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr., Santa Q,BBSO 87505	CD	
SUNDRY NOTICES	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
DIFFERENT RESERVOIR. USE "APPLICAT	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO ION FOR PERMIT" (FORM C-101) FOR SUCH	Name
PROPOSALS.) 1. Type of Well: Oil Well Ga		LANGLIE MATTIX PENROSE SAND
da da	S Well Other WIW	
		8. Well Number 182
2. Name of Operator LEGACY	•	9. OGRID Number 240974 /
£	10848 , TX 79702	10. Pool name or Wildcat LANGLIE-MATTIX SR QN GRBG
4. Well Location		
Unit Letter L :1980_	feet_from theSOUTH line and	330feet from theWestline. /
Section 26	Township 22S Range 37E	NMPM LEA County
11.	Elevation (Show whether DR, RKB, RT, 0 3322' GR	SR, etc.)
Pit or Below-grade Tank Application or C	losure	
Pit typeDepth to Groundwate	rDistance from nearest fresh water well_	Distance from nearest surface
water		
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material
NOTICE OF INTEN	_	BSEQUENT REPORT OF:
NOTICE OF INTEN PERFORM REMEDIAL WORK ☐ PLU	TION TO: SU	BSEQUENT REPORT OF: ORK
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA	TION TO: IG AND ABANDON REMEDIAL WO	BSEQUENT REPORT OF: ORK
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL	TION TO: IG AND ABANDON REMEDIAL WO ANGE PLANS COMMENCE D CASING/CEME	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOE Approved for plugging of well bore only. Liability under bond is retained pending receipt
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL OTHER:	TION TO: IG AND ABANDON REMEDIAL WO ANGE PLANS COMMENCE D CASING/CEME	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOB Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or complete estimated date of starting any	TION TO: IG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME TIPLE COMPL OTHER: OTHER: Deed operations. (Clearly state all pertinent proposed work). SEE RULE 1103. For M	BSEQUENT REPORT OF: ORK ALTERING CASING ALTERING OPNS. PAND A NT JOE Approved for plugging of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under the page and give postingent dates.
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or complete estimated date of starting any proposed completion	TION TO: IG AND ABANDON REMEDIAL WO COMMENCE DE COMMENCE DE CASING/CEME TIPLE COMPL OTHER: DED COMMENCE DE CASING/CEME OTHER: DEC CASING/	BSEQUENT REPORT OF: ORK ALTERING CASING ALTERING OPNS. PAND A NOT JOB Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under which may be found at OCD Web Page under the part of the page under the
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN	TION TO: IG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME TIPLE COMPL OTHER: OTHER: Proposed work). SEE RULE 1103. For Mon or recompletion.	BSEQUENT REPORT OF: ORK ALTERING CASING ALTERING OPNS. PAND A NOT JOB Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under details, and give perfinent dates cancluding ultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER.
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245" CIRCUI	TION TO: IG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME TIPLE COMPL OTHER: OTHER:	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOB Approved for plugging of well hore only. Liability under bond is rotained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under and government dates cancluding ultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER.
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 3	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOB Approved for plugging of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under apply given perfinent dates, including ultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER. JMP. SDFN 2 25 SX CLASS C NEAT CMT @ 3245'. WOC FOR 4 NEAT CMT @ 2457'. POOH ABOVE CMT. SDFN.
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245" CIRCUL HRS RIH TO TAG PLUG @ 3100°. 12/15/08- RIH W/ TBG TO TAG PLUG @ 12/16/08- RUWL. RIH TO CUT 7" CSG @ 12/16/08- RUWL. RIH	TION TO: IG AND ABANDON REMEDIAL WORKED PLANS COMMENCE DE CASING/CEME OTHER: OTHER:	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOB Approved for plugging of well hore only. Liability under hond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under details, and give perfinent dates, and cluding ultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER. OMP. SDFN 2 25 SX CLASS C NEAT CMT @ 3245'. WOC FOR 4 NEAT CMT @ 2457'. POOH ABOVE CMT. SDFN.
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 2 12/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG @ 988". RUWI	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NOT JOB Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under details, and give perfinent dates, and under under wellbore 4 LD 103 JTS. 2 3/8" IPC TBG & PACKER. JMP. SDFN 2 25 SX CLASS C NEAT CMT @ 3245'. WOC FOR 4 NEAT CMT @ 2457'. POOH ABOVE CMT. SDFN. WHE. SDFN NINGE 2 STC 23# 7" CSG. SDFN
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 21/16/08- RUWL. RIH TO CUT 7" CSG @ 21/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG @ 988'. RUWI NEAT CMT. SD WOC OVERNIGHT	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK ALTERING CASING ALTERING OPNS. PAND A NOT JOB Approved for plugging or well hore only. Liability under hond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which must be found at OCD Web Page under and given pentinent dates, and given pentinent dates, and under pultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER. JMP. SDFN P 25 SX CLASS C NEAT CMT @ 3245'. WOC FOR 4 NEAT CMT @ 2457'. POOH ABOVE CMT. SDFN. WHE. SDFN WHE. SDFN WINGE 2 STC 23# 7" CSG. SDFN M&P 80 SX CLASS C NEAT CMT. SD. WOC 4 HRS. H TO SET PKR @ 100'. SQUEEZE 250 SX CLASS C
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 212/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG @ 988'. RUWI NEAT CMT. SD WOC OVERNIGHT. 12/18/08- RIH TO TAG PLUG. DID NOT SPOT 20 SX CLASS C NEAT CMT. AND CLEAN LOCATION.	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOB Approved for plugging or well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under and government dates and cluding ultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER. JMP. SDFN 2 25 SX CLASS C NEAT CMT @ 3245". WOC FOR 4 NEAT CMT @ 2457'. POOH ABOVE CMT. SDFN. WHE. SDFN NGE 2 STC 23# 7" CSG. SDFN M&P 80 SX CLASS C NEAT CMT. SD. WOC 4 HRS. H TO SET PKR @ 100'. SQUEEZE 250 SX CLASS C CMT WOC FOR 4 HRS. RIH TO TAG PLUG @ 48'. PLETE. INSTALL PXA MARKER, BACKFILL CELLAR
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245" CIRCUL HRS RIH TO TAG PLUG @ 3100". 12/15/08- RIH W/ TBG TO TAG PLUG @ 212/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG @ 988". RUWI NEAT CMT. SD WOC OVERNIGHT 12/18/08- RIH TO TAG PLUG @ 10D NOT SPOT 20 SX CLASS C NEAT CMT. AND CLEAN LOCATION. I hereby certify that the information above	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK ALTERING CASING RILLING OPNS. PAND A NT JOB Approved for plugging or well hore only. Liability under hond is rotained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under and government dates and cluding ultiple Completions: Attach wellbore & LD 103 JTS. 2 3/8" IPC TBG & PACKER. JMP. SDFN 2 25 SX CLASS C NEAT CMT @ 3245". WOC FOR 4 NEAT CMT @ 2457'. POOH ABOVE CMT. SDFN. WHE. SDFN M&P 80 SX CLASS C NEAT CMT. SD. WOC 4 HRS. H TO SET PKR @ 100". SQUEEZE 250 SX CLASS C CMT WOC FOR 4 HRS. RIH TO TAG PLUG @ 48'. PLETE. INSTALL PXA MARKER, BACKFILL CELLAR
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL PULL OR ALTER CASING MUL OTHER: 13. Describe proposed or complete estimated date of starting any p diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 2 12/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG @ 988'. RUWI NEAT CMT. SD WOC OVERNIGHT. 12/18/08- RIH TO TAG PLUG. DID NOT SPOT 20 SX CLASS C NEAT CMT. AND CLEAN LOCATION. I hereby certify that the information abor pit or below-grade tank has been/will be const alternative OCD-approved plan	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 3100'. 12/15/08- RIWL. RIH TO CUT 7" CSG @ 12/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG. DID NOT SPOT 20 SX CLASS C NEAT CMT. AND CLEAN LOCATION. I hereby certify that the information aborpit or below-grade tank has been/will be constalternative OCD-approved plan . SIGNATURE KENT WILLIAM:	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 3100'. 12/15/08- RIWL. RIH TO CUT 7" CSG @ 12/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG. DID NOT SPOT 20 SX CLASS C NEAT CMT. AND CLEAN LOCATION. I hereby certify that the information aborpit or below-grade tank has been/will be constalternative OCD-approved plan . SIGNATURE	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK
NOTICE OF INTEN PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON MUL OTHER: 13. Describe proposed or complete estimated date of starting any proposed diagram of proposed completion 12/10/08- MIRU BCM & ASSOC PLUGGIN RIH W/ 25 JTS. SDFN 12/11/08- NDWHE. RIH W/ 104 JTS. TBG. 12/12/08- SET 7" CIBP @ 3245' CIRCUL HRS RIH TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 3100'. 12/15/08- RIH W/ TBG TO TAG PLUG @ 12/16/08- RUWL. RIH TO CUT 7" CSG @ 12/17/08- POOH & LD REMAINDER OF RIH TO TAG PLUG @ 988'. RUWI NEAT CMT. SD WOC OVERNIGHT. 12/18/08- RIH TO TAG PLUG. DID NOT SPOT 20 SX CLASS C NEAT CMT. AND CLEAN LOCATION. I hereby certify that the information above pit or below-grade tank has been/will be constructed alternative OCD-approved plan . SIGNATURE KENT WILLIAM: For State Use Only	TION TO: IG AND ABANDON	BSEQUENT REPORT OF: ORK