

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

JAN 05 2009

HOBBSD

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-23997 ✓
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B9950
7. Lease Name or Unit Agreement Name State B ✓
8. Well Number 5 ✓
9. OGRID Number 012254 ✓
10. Pool name or Wildcat 03820 Bagley Permopenn North ✓

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
JPH OIL PRODUCERS - Jimmy Hodge

3. Address of Operator
P.O. Box 565 Lovington, NM 88260

4. Well Location
Unit Letter L : 1980' feet from the South line and 660' feet from the West line
Section 10 Township 12S Range 33E NMPM 12A County ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4253

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Rig up Tyler well Ser.
2. Pull 261 joints of tubing
3. Pull slip on 5 1/2" Casing & Free point Casing
4. Cut & remove as much 5 1/2" Casing as possible
5. Cement 50' above 5 1/2" ~~cut~~ pulled on outside of 5 1/2" (open Hole) & 50' Cement inside 5 1/2" - TAG PLUG
6. Free point 8 5/8" Casing Cut & remove as much 8 5/8" as possible
7. Cement 50' above 8 5/8" pulled & 50' inside 8 5/8" Casing TAG PLUG
8. Cement 350' of 13 3/8" Surface Casing to Surface
9. install Dry Hole marker & Clean Location

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Jimmy Hodge TITLE operator DATE 6-30-08

Type or print name
For State Use Only

E-mail address:

Telephone No.

APPROVED BY: Tom W. Hill
Conditions of Approval (if any):

TITLE DISTRICT 1 SUPERVISOR DATE JAN 13 2009

The Oil Conservation Division **Must be notified**
24 hours prior to the beginning of plugging operations

Def: 6-25-07

CURRENT WELL-BORE

unit 2 - 1980 "FSL + 660" from D. FSL

ELEVATION GR. 4253.6

